

INDEX

- Acceptable quality levels (AQL)
 - acceptable sampling, 468
 - standardized sampling plan, 497
- Acceptance control chart, 341–343
- Acceptance number, 13
- Acceptance sampling plan
 - average outgoing quality (AOQ), 475–476
 - average outgoing quality limit (AOQL), 477
 - average sample number (ASN), 478–480
 - average total inspection (ATI), 477–478
 - double sampling plan, 473–474
 - history of, 5
 - meaning of, 12
 - multiple sampling plan, 474
 - operating characteristic curve, 469–473
 - pros and cons of, 468, 474–475
 - risks in sampling plan, 468–469
 - sample size, 472–473
 - single sampling plan, 473
 - time for, 467–468
 - variable sampling, 507–518
- Accumulation analysis, 646–648
- Accuracy, of data set, 157
- Act stage, of Deming cycle, 64–65
- Activity based costing (ABC), 19–22
- Adams, B. M., 321, 367
- Additive law, of probability, 153
- Adjustment factor, 616
- Aliases, 608, 609–612
- Alias structure, 648
- Alt, F. B., 346, 367
- Alternate fraction, 608
- Alternative hypothesis, 199, 201
- American National Standards Institute (ANSI)/
 - American Society for Quality (ASQ).
 - See entries under ANSI/ISO/ASQ
- American Society for Quality (ASQ), 17, 44, 288
 - history of, 5
- Analysis of variance (ANOVA), 567–572
 - differences among treatment means, 569–571
 - F*-statistic, 569–571
 - Minitab for, 570–571, 576, 593–594
- Anderson-Darling test, 237–238
- ANSI/ISO/ASQ Q9000 Standard*, 7, 133–134
- ANSI/ISO/ASQ Standard A3534-2*, 288
- ANSI/ISO/ASQ Standard A8402*, 9, 44
- ANSI/ISO/ASQ Standard QS 9000*, 134
- ANSI/ISO/ASQ Standard Z1.4*, 497, 526
- ANSI/ISO/ASQ Standard Z1.9*, 518, 526
- Appraisal costs, 23
- Arnold, S. F., 198, 227, 234, 261
- Arrays, orthogonal, 629–639
- AS 9100 Standard*, 134
- Assemblies, tolerances on, 445–451
- Association, measures of, 246–247
 - mean-squared contingency, 247
 - Cramer's *V*, 247
- AT&T, 304, 367
 - benchmarking, 111
- Attribute charts
 - advantages of, 370
 - c*-chart, 387–390
 - for demerits per unit, 393–396
 - disadvantages of, 370–371
 - np*-chart, 384–387
 - for number of nonconforming items, 384–387
 - for number of nonconformities, 387–390
 - for number of nonconformities per unit, 390–393
 - operating characteristic curves, 400–403
 - p*-chart, 372–384, 400–401
 - preliminary decision making, 371–372
 - process capability analysis based on, 441–445

- Attribute charts (*continued*)
 for proportion of nonconforming items, 372–384
 sample size, 371–372
U-chart, 393–396
u-charts, 390–393
- Attributes
 levels of, 370
 of quality, 7, 8
- Attribute sampling plan
 chain sampling plan, 501–503
 Deming's *kp* rule, 504–507
 Dodge–Romig plans, 497–501
 double sampling plan, 490–495
 multiple sampling plan, 496
 sequential sampling plan, 503–504
 single sampling plan, 483–490
 standardized sampling plan, 497–501
- Auditors, types of, 115
- Automotive Industry Action Group (AIAG), 129
- Availability, 534
- Average outgoing quality (AOQ), 475–476
- Average outgoing quality limit (AOQL), 476–477
 Dodge–Romig plans, 500–501
- Average run length (ARL)
 control charts, 277–279, 400
 cumulative sum chart (cusum charts) for, 326–328
- Average sample number (ASN), 478–480, 492–493
- Average total inspection (ATI), 477–478, 493–494
- Balanced experiment, 567
- Balanced scorecard (BSC), 98–100
 diagnostic measures, 98
 outcome measures, 99
 performance drivers, 98
 perspectives of, 98
 strategic measures, 99
- Banks, J., 186, 227
- Barnard, G. A., 324, 367
- Bathtub curve, phases in, 530
- Baye's rule, 480–483
 posterior probability, 480–481
 prior probability, 480
- Beaver, R., 189, 208, 227
- Behrens-Fisher problem, 194
- Benchmarking, 111–114
 benefits of, 111
 impetus for, 113–114
 models for, 111
- Besterfield, D. H., 279, 288, 394, 414, 530, 558
- Binomial distribution
 calculation of, 177–179
 cumulative, table for, 665–669
 hypergeometric distribution approximation, 211
 normal approximation, 212
 Poisson approximation, 211
- Blichke, W. R., 534, 558
- Blocking, experimental design, 565
- Boudot, J. R., 628, 663
- Bowker, A. H., 328, 367
- Box, G. E., 560, 565, 567, 612, 628, 649, 662
- Box-Cox transformation, 444
- Box plots, 232–234
 notched box plot, 234
- Boyles, R. A., 430, 432, 464
- Bunches, control charts, 307
- Calibration
 of measurement instrument, 158
- Campanella, J., 23, 44
- Capability ratio (CR), 427–428
- Cause-and-effect diagrams, 122–123
 cause enumeration, 122
 dispersion analysis, 122
 fishbone diagrams, 122
 history of, 6
 Ishikawa diagrams, 122
 process analysis, 122
 use of, 122
- Cause enumeration, 122
- c*-chart, 387–390
 with no standard given, 388
 and Poisson distribution, 387–388, 390
 process capability measurement, 444
 with standard specified, 388
- Center line
 control charts, 266, 269
 factors for computation of, 685
- Central Limit Theorem, 189, 204, 268
- Chain sampling plan, 501–503
 operating characteristic curve, 501–503
- Chambers, J. M., 232, 260
- Chance-failure phase, 530
- Change management, and benchmarking, 113
- Check stage, of Deming cycle, 64
- Chi-squared distribution, 197, 244–245, 246
 chi-square values for right-tail area, 677–678
- Chi-squared test, 244–245, 246
- Chou, Y., 240, 260
- Chronic problems, 84
- Clarke American Checks, Inc, case study, 85–88
 Malcolm Baldrige National Quality Award, 85
- Clearance fits, 449–450
- Clement, J., 283, 288
- Cleveland, W. S., 232, 260
- Clustering, 235–236
- Cluster sample, 249–250
- Cochran, W. G., 423, 464
- Cohen, L., 15, 44
- Common causes, nature of, 18, 84, 267
- Competitive position, and quality
 improvement, 34
- Complementary events, probability, 152
- Completely randomized design, 566–572
 two-factor factorial experiment, 586–589
- Complex systems, and reliability, 539–540
- Components in parallel, and reliability, 536–539

- Components in series, and reliability, 534–536
- Compound events, probability, 151–153
- Confidence interval, 190–199
 - for difference between two binomial proportions, 196
 - for difference between two means, 194–195
 - for the mean, 192–194
 - one and two-sided, 191–192
 - for proportion, 195–196
 - for ratio of two variances, 198–199
 - for variance, 196–198
- Confirmation experiments, 617
- Conformance, quality of, 10
- Conformity quality audit, 115
- Confounding
 - meaning of, 606
 - in 2^k factorial experiment, 606–607
- Constant failure rate, exponential distribution, 531–532
- Consumer's risk
 - acceptance sampling, 468–469
 - and OC curve, 470–472, 543
 - single sampling plan, 486–490
- Contingency tables, 245–246, 247
- Continuous quality improvement practices, 110–127
 - benchmarking, 110–113
 - and innovation, 110–111
 - quality audits, 114–116
 - and vendors, 116–120
- Continuous quality improvement tools
 - cause-and-effect diagrams, 122–123
 - flow charts, 121–122
 - Pareto diagrams, 120–121
 - scatter plots, 123
- Continuous variables, 157
- Contrast
 - contrasts of totals, 599–602
 - defining contrast, 608
 - factorial experiments, 596–602
 - orthogonal contrasts, 598–602
- Control chart construction
 - acceptance control chart, 341–343
 - control limits, 293–294, 299–300
 - cumulative sum chart (cusum charts), 321–329
 - exponentially weighted moving average (EWMA) chart, 332–335
 - geometric moving-average control chart, 332–335
 - Hotelling's T^2 control chart, 345–349
 - for highly conforming processes, 397–400
 - for individual units, 315–318
 - for mean and range, 293–310
 - for mean and standard deviation, 310–315
 - Minitab, 296–297
 - modified control chart, 338–341
 - moving-average control chart, 329–332
 - from moving ranges, 316
 - multivariate control charts, 343–354
 - R-chart, 294, 300
 - sample size, 298
 - s-chart, 311–313
 - short production runs, 319–321
 - standardized control charts, 298–299
 - steps in development, 293–296
 - trend chart (regression control chart), 335–338
 - \bar{X} -chart, 293–310
 - Z-MR chart, 319–321
- Control chart patterns
 - bunches/groups, 307–308
 - cyclic patterns, 306–307
 - freaks, 307
 - gradual shifts in level, 305
 - interaction patterns, 309–310
 - mixture patterns, 307–308
 - natural patterns, 304
 - stratification patterns, 308–309
 - sudden shifts in level, 304–305
 - trending pattern, 306
 - wild patterns, 307–308
- Control charts
 - for attributes. *See* Attribute charts
 - average run length, 277–279
 - benefits of, 266, 268
 - characteristics for investigation, 290–292
 - construction of. *See* Control chart construction
 - control limits effects, 275–276
 - control limits selection, 269
 - data recording forms, 293
 - history of, 5
 - instant-of-time method for sample observations, 279
 - interpretation of plots, 282–283, 304–310
 - lines, meaning of, 267–268
 - maintenance of, 284–285
 - measuring instrument selection, 292
 - and on-line process control, 268
 - operating characteristic curve, 274–275
 - out-of-control points, cause of, 284, 301–302
 - out-of-control process identification, 280–282
 - pattern analysis, steps in, 280–282
 - pre-construction decisions, 292–293
 - process capability analysis based on, 442–445
 - purpose of, 265
 - rational samples, selection of, 279–280, 292
 - sample size, 279, 292
 - sample size effects, 276–277
 - sampling frequency, 279–280, 292
 - for service industries, 343
 - statistical process control (SPC), 268
 - and Type I error, 271
 - and overall Type I errors, 282–283
 - and Type II errors, 271–272
 - variation, causes of, 267
 - warning limits, 276
- Control limits
 - control chart construction, 293–296, 299–300
 - for control charts, 266, 289
 - factors for computation of, 685
 - compared to specification limits, 416–417

- Convenience sampling, 53
- Corporate culture, 58
- Corrective action, 294–295
 - process of, 78
- Correlation coefficient, 170–171
 - calculation of, 170
 - degrees of correlation, types of, 170–171
- Cost base index, quality cost measure, 26
- Costs, product and service, 19–22
 - batch-level, 20
 - direct, 19
 - drivers of, 19
 - indirect, 19
 - product/service-level, 20
 - production/service sustaining, 20
 - unit-level, 20
- Count data, analysis, 244–247
- C_p index, 423–424, 429–433, 441
- C_{pk} index, 425–427, 429–434
- Critical to quality (CTQ) characteristics, 102, 133
- Crosby, Philip B., 7, 44, 75–78, 90
 - absolutes of quality management, 76
 - background information, 75
 - 14–step quality improvement plan, 76–78
 - quality management grid, 77
- Cumulative binomial distribution, table for, 665–669
- Cumulative distribution function, 175
- Cumulative Poisson distribution, table for, 670–671
- Cumulative sum chart (cusum charts), 321–329
 - for average run length (ARL), 327–329
 - process variability, for, 329
 - pros/cons of, 321–322
 - tabular method, 322–324
 - V-mask parameters, 325–327
- Customers
 - Deming's view of, 59
 - Juran's view, 79–80
 - needs of, 15
 - and quality function deployment (QFD), 103–106
 - satisfaction, 48
 - and total quality management (TQM), 95
- Cyclic patterns, control charts, 306–307

- Data collection, 156–158
 - accuracy and precision, 157–158
 - continuous and discrete variables, 157
 - by observation, 156
- Debugging phase, 530
- Defect
 - Deming's view of, 61
 - meaning of, 9
- Defining contrast, 608
- Degrees of freedom, 193, 194
- Dehnad, K., 613, 663
- Demerits per unit, chart for, 393–396
- Deming's *kp* rule, 504–507
 - basic assumptions in, 504–505
 - evaluation of, 506–507
- Deming, W. Edwards, 5, 56–75, 91, 504
 - deadly diseases of, 72–75
 - Deming cycle, 63–64
 - extended process of, 57–58
 - 14 points for management, 58–72
 - philosophy of, 56–57
 - System of Profound Knowledge, 56–57
- Department of Defense (DOD), 5
- Descriptive statistics, nature of, 156
- Design, quality of, 9–10
- Design resolution, 2^k factorial experiment, 609–610
- Diagnostic arm, 81
- Direct observation, 156
- Discrete variables, 157
- Dispersion analysis, 122
- Dodge, H. F., 3, 497, 526
- Dodge–Romig plans, 497–501
 - average outgoing quality limit (AOQL), 500–501
 - limiting quality level, 498–499
- Do stage, of Deming cycle, 64
- Double-blind study, 566
- Double sampling plan
 - acceptance sampling, 473–474
 - attribute sampling, 490–495
 - average sample number, 478–480, 492
 - average total inspection curve, 477–478, 493–494
 - design of, 493–495
 - OC curve, 490–492
- Draper, N. R., 560, 565, 649, 662
- Duncan, A. J., 189, 208, 227, 237, 260, 423, 464, 515, 526

- Eastman Chemical Company, and total quality management (TQM), 97
- Eco-Management and Auditing Scheme (EMAS), 36
- Effectiveness, service business, 50
- Efficiency, service business, 50
- Ehrlich, B. H., 131, 146
- Electronic data interchange, 31
- El-Haik, B., 131, 146
- Elsayed, A., 613, 663
- Empirical distribution plots, 229–234
- Employee
 - quality and service industries, 50–52
- Enterprise resource planning, 31–32
- Environmental management, 36–37
 - benefits of, 36–37
 - scope of activities, 36
 - standards development, 36
- Error bound, 250–252
- Errors in sampling, 248
 - misspecification, 248
 - nonresponse, 248
 - random variation, 248

- Ethical characteristics, of quality, 8
- Expected opportunity loss, 482–483
- Expected value, 175
of perfect information (EVPI), 482
- Experimental design
analysis of variance (ANOVA), 567–572
balanced/unbalanced experiment, 567
blocking, 565
completely randomized design, 566–572
confirmation experiments, 617
design elements, 565
double-blind study, 566
factorial experiments, 585–613
fixed effects model, 566
Latin square design, 577–585
measurement bias, 565–566
random effects model, 566
randomization, 564–565
randomized block design, 572–577
replication, 564
single-blind study, 566
usefulness of, 560–561
variables, 562–564
See also Factorial experiments; Taguchi method
- Experimental error, 561
- Experimental unit, in experiment, 561
- Exponential distribution
calculation of, 184–186
for model failure rate, 530–532, 535, 537
standby system, 540–542
systems with components in parallel,
537–538
systems with components in series, 535–536
systems with components in series/
parallel, 539–540
- Exponentially weighted moving average (EWMA)
chart, 332–335
- Extended process, Deming's view, 57–58
- External failure costs, 24
- External noise, 615
- Factorial experiments, 585–613
contrast, role of, 596–602
 2^k factorial experiment, 602–613
two-factor with completely randomized design,
586–589
two-factor with randomized block design, 590–596
uses of, 585–586
- Factors, in experiment, 560
- Failure mode and effects criticality analysis (FMECA),
127–133
risk priority number (RPN), 128
- Failure-rate function
exponential distribution, 531–532
Weibull distribution, 532–534
- Failure-terminated test, 544–547
with *Handbook H-108*, 548
- F-distribution*, 198
- F*, values for right-tail area, 679–684
- Federal Express Company, performance measures
of, 117
- Feigenbaum, A. V., 5, 6, 44
- Fellers, G., 58, 91
- Fishbone diagrams, 122
history of, 6
- Fitzimmons, J. A., 48, 91
- Fitzimmons, M. J., 48, 91
- Fixed effects model, 566
- Flow charts, use of, 121
- Ford Motor Company, 37
- Foreman Quality Control period, 4
- Forms 1 and 2
variable sampling plans, 515, 517
- 14 points for management, of Deming, 58–72
- 14-step quality improvement plan, Crosby's, 76–78
- Freaks, control charts, 307
- Frequency distribution, 230–231
- Frequency histogram, 230–231
- F*-statistic, 569–571
analysis of variance (ANOVA), 569–571
Latin square design, 581–584
randomized block design, 574–576
- Gage, study of, 435–440
bias, 436
design of, 437–438
linearity, 436
R&R, 435–436, 437
repeatability, 435–436
reproducibility, 435–436
stability, 437
- Gamma distribution, 187–188
probability density function, 187
- Gap analysis, 112
- Garvin, D. A., 7, 45
- Generator, in 2^k factorial experiment, 608
- Geometric moving-average control chart, 332–335
- Gitlow, H. S., 58, 91
- Gitlow, S. J., 58, 91
- Goals
Crosby's view, 78
Deming's view, 68–69, 73–74
- Godfrey, A. B., 311, 367, 400, 414, 560, 663
- Goh, T. N., 398, 414
- Goodness-of-fit tests, 237–239
- Graeco-Latin square design, 629
- Graphical methods
box plots, 232–234
cause-and-effect diagrams, 122–123
frequency distribution, 230–231
histogram, 230–231
matrix plots, 125–126
multivariable charts, 123–125
normal probability plots, 237–238

- Graphical methods (*continued*)
 Pareto diagrams, 120–121
 run charts, 235–236
 scatter diagrams, 123, 124
 stem-and-leaf plots, 231–232
 three-dimensional scatter plot, 125, 127
- Grubbs, F. E., 485, 526
- Gunter, B. H., 425, 464, 560, 562, 662–663
- Half-fraction, of 2^k factorial experiment, 608–609
- Hawkins, D. M., 321, 367
- Henley, E. J., 186, 227, 532, 558
- Highly conforming processes
 control charts, 396–400
 exponential distribution, use of, 397–398
 geometric distribution, use of, 398
 power transformation, 397
 probability limits, 398–399
- Histogram, 229–231
- Hotelling, H., 345, 367
- Hotelling's T^2 control chart, 345–349
 construction of, 346–349, 350–353
 control ellipse procedure, 344–345
 percentile points, values of, 345
- House of quality, 104
- Hsiang, T., 613, 663
- Human factors, service industries, 50
- Hunter, J. S., 560, 567, 612, 628, 662, 663
- Hunter, W. G., 560, 567, 612, 662
- Hurley, P., 429, 464
- Hyatt Hotel Corporation, performance standards, 100
- Hybrid orthogonal arrays, 638–639
- Hypergeometric distribution, 176–177, 211
- Hypothesis testing, 199–210
 alternative hypothesis, 199, 201
 correlation coefficient, 205
 difference between two means from paired samples, 207
 for difference between two binomial proportions, 208–209
 of difference between two means, 205–207
 of mean, 204
 null hypothesis, 199, 201, 203
 one-tailed test, 201
 for proportion, 207–208
 for ratio of two variances, 210
 steps in, 203–204
 test statistic, 199
 two-tailed test, 201
 Type I/Type II errors, 202–203
 for variance, 209–210
- IBM Direct, and total quality management (TQM), 97
- Incomplete block design, Latin square design as, 578
- Independent events, probability, 154
- Indirect observation, 156
- Infant-mortality phase, 530
- Inferential statistics, 188–210
 confidence interval, 191–199
 hypothesis testing, 199–210
 interval estimation, 190–191
 nature of, 156
 point estimation, 190
 sampling distributions, 189–190
- Innovation
 benefits of, 110
 and continuous improvement, 110–111
 Deming's view, 66–67
Inspection and Quality Control Handbook H108, 5
- Inspection Quality Control period, 4
- Instant-of-time method, for sample observations, 279
- Interaction patterns, control charts, 309–310
- Interactions, experiments, 562–564
- Interference fits, 450
- Internal failure costs, 23
- Internal noise, 615
- International Organization for Standardization (ISO), 7
 vendor certification, 119
See also entries under ISO and ANSI/ISO/ASQ
- Interquartile range, calculation of, 165–166
- Interval estimation
 calculation of, 190–191
 confidence interval, 191–199
- Interval scale, 158
- Ishikawa diagrams, 122
 history of, 6
- ISO 1800 Standard*, 135
- ISO 9000-9004*, 133–134
- ISO 14000: An International Environmental Management Standard*, 36
ISO 14001, 36
ISO 14010, 36
ISO 14020, 36
ISO 14031, 36
ISO 14040, 36
ISO 14060, 36
ISO 19011, 133
ISO/TS 16949 Standards, 134
- Japan
 and Deming, 5
 and Juran, 78
- Johnson, N. L., 240, 261, 428, 429, 464
- Joint Commission on Accreditation of Healthcare Organizations, 411, 414
- Judgment sampling, 53
- Juran Institute, 78
- Juran, Joseph M., 5, 7, 45, 78–82, 91
 background information, 78
 quality trilogy, components of, 79–82
- Kackar, R. N., 614, 628, 663
- Kane, V. E., 379, 419
- Kano model, 15–16

- Kaplan, R. S., 98, 146
 Kendall, M. G., 198, 227, 234, 261
 Kotz, S., 428, 464
k-method, variable sampling plans, 515, 517
kp rule, 61, 504–507
 Kumamoto, H., 186, 227, 532, 558
 Kuralmani, V., 398, 414
 Kurtosis coefficient, 167
 calculation of, 167–169
 Kushler, R. H., 429, 464
 Kutner, M. H., 170, 227
- Labor base index, quality cost measure, 26
 Latin square design, 577–585
 ANOVA table for, 580, 584
 difference among treatment means, 581–585
 F-statistic, 581
 Graeco-Latin square design, 629
 as incomplete block design, 578
 pros/cons of, 578
 randomization of, 578–579
 Leadership, Deming's view, 66
 Leadership Through Quality program, 97
 Lefevre, H. L., 50, 91
 Leon, R. V., 628, 663
 Levels, in experiment, 560–561
 Lieberman, G. J., 328, 367, 515, 526
 Life-cycle curve, 530
 phases in, 530
 Life testing plans, 544–554
 failure-terminated test, 544–548
 sequential life testing plan, 545
 time-terminated test, 547, 548–554
 Limiting quality level
 in acceptance sampling, 468–469
 Dodge–Romig plans, 498–499
 Linear graphs, 629–639
 and orthogonal arrays, 629–639
 L. L. Bean, benchmarking, 112
 Log normal distribution, 188
 cumulative distribution function, 188
 probability density function, 188
 scale parameter, 188
 shape parameter, 188
 Loss functions, 65
 and larger values, 622–624
 manufacturing tolerances, 620–621
 and smaller values, 621–622
 Taguchi method, 617–624
 Lot proportion nonconforming, variable
 sampling plans for, 514–518
 Lowe, T. A., 82, 91
 Lower capability index, 424–425
 Lower control limit, control charts, 266
 Lower tolerance limits, 416
 natural tolerance limits, 419–420
 Lucas, J. M., 321, 367
- Mage, D. T., 423, 464
 Malcolm Baldrige National Quality Award, 37,
 135–138
 eligibility categories, 135–136
 eligibility criteria, 135–136
 evaluation criteria, 136–138
 The Bama Companies, Inc., 37–39
 and vendor certification, 120
 Management
 Deming's view, 56, 58, 60, 73–75
 Management practices
 continuous improvement, 110–127
 performance standards, 100–101
 quality function deployment (QFD),
 103–110
 total quality management (TQM), 94–96
 Managing supplier relationships, 30–32
 Manufacturing industry, 136
 compared to service industry, 48–50
 Manufacturing tolerances, 620–621
 Marcus, P. A., 36, 45
 Mason, R. L., 240, 260
 Massey, F. J., Jr., 237, 261, 423, 464
 Mass inspection, limitations of, 60
 Mating parts, 449–451
 clearance fits, 449–450
 interference fits, 450
 transition fits, 450–451
 Matrix plots, 125–126
 Minitab software, 126
 Mazzeo, J. M., 82, 91
 McGill, R., 234, 261
 Mean
 calculation of, 159
 confidence interval, 192–195
 hypothesis testing, 204–207
 population mean, 159
 sample mean, 159
 trimmed mean, 161
 Mean time between failure, exponential
 distribution, 531
 Mean time to failure
 exponential distribution, 531–532
 Weibull distribution, 532–533
 Mean time to repair, 534
 Measurement error
 gage repeatability, 435–436, 438–440
 gage reproducibility, 435–436, 438–440
 and precision-to-tolerance ratio, 434–435, 437
 Measurement scales, 158–159
 interval scale, 158
 nominal scale, 158
 ordinal scale, 158
 ratio scale, 158–159
 Measurement systems, evaluation of, 436–440
 accuracy of, 436
 metrics, 437

- Measures of association, 169–172
 - correlation coefficient, 170–171
- Measures of central tendency, 159–161
 - mean, 159
 - median, 159–160
 - mode, 160–161
 - trimmed mean, 161
- Measures of dispersion, 161–166
 - interquartile range, 165–166
 - range, 161–162
 - standard deviation, 163–165
 - variance, 162–163
- Measurement bias, experimental design, 565–566
- Median, calculation of, 159–160
- Mendenhall, W., 189, 208, 227
- Military Standards. *See* entries under MIL-STD
- MIL-STD-105E, 5, 497
- MIL-STD-414, 5, 518–519
- MIL-STD-690B, 544
- Minitab software
 - analysis of variance (ANOVA), 570–571, 576, 593–594
 - attribute control charts, 377, 389, 392–393
 - confidence intervals, 172, 197
 - hypothesis testing, 207
 - matrix plots, 126
 - Pareto diagrams, 120
 - probability distribution identification, 238–239
 - probability plotting, 237–238
 - process capability analysis, 438, 442–443, 445
 - sample size problems, 254
 - three-dimensional scatter plots, 127
 - variables control charts, 296, 318, 320–321, 324–325, 327, 354
- Mission statements, Deming’s view, 59, 73–74
- M-method, variable sampling plans, 515, 517
- Mode, calculation of, 160–161
- Modified control chart, 338–341
- Montgomery, D. C., 311, 367, 560, 648, 663
- Motorola, Inc.
 - benchmarking, 111
 - six-sigma quality, 100–103
- Moving-average control chart, 329–332
 - exponentially weighted moving average (EWMA) chart, 332–335
 - geometric moving-average control chart, 332–335
 - moving-average span, 333
 - step in construction of 329–332
- Moving range, control charts, 316–318
- Multinomial experiment, 244
- Multiple sampling plan
 - acceptance sampling, 474
 - attribute sampling, 496
- Multiplicative law, of probability, 153–154, 155
- Multivariable charts, 123–125
 - types of, 124
- Multivariate control charts, 343–354
 - generalized variance chart, 349–350, 353–354
 - quality characteristics, control of, 343–345
 - T² control chart, 345–349, 350–353
- Murthy, D. N. P., 534, 558
- Mutually exclusive events, probability, 154, 156
- Nachtsheim, C. J., 170, 227
- Nair, V. N., 613, 648, 663
- National Institute of Standards and Technology (NIST), 135
- Natural tolerance limits, 419–420
 - upper and lower natural tolerance limits, 419–420
- Nelson, L. S., 299, 367, 397, 414
- Nelson, W., 423, 464
- Neter, J., 170, 227
- Neyman, J., 513, 526
- Noise
 - internal and external, 615
 - noise factors in experiment, 561
- Nominal scale, 158
- Nonconformance rate, and process capability indices, 441
- Nonconforming items
 - chart for number of items, 384–387
 - chart for proportion of items, 372–384
 - cost of correction, 23
 - meaning of, 8, 369
- Nonconformity
 - chart for number of, 387–390
 - chart for number of per unit, 390–393
 - classification of defects, 394
 - meaning of, 8, 369
 - service industries, 51
- Nonparametric statistical tolerance limits, 454–455
- Normal distributions
 - approximation to binomial, 212
 - approximation to Poisson, 212–213
 - calculation of, 180–184
 - standard normal distribution, table for, 672–674
 - statistical tolerance limits based on, 453–454
- Normal probability plots, 237–239
- Normann, R., 50, 91
- Norton, D. P., 98, 146
- Notched box plot, 234
- np*-chart, 384–387
 - limitations of, 385
 - with no standard given, 385
 - process capability measurement, 444
 - with standard specified, 385
- Null hypothesis, 99, 201, 208
- Observation, for data collection, 156
- Off-line quality control, 12, 613
- O’Hagan, A., 198, 227, 234, 261

- 100% sampling, 53
- One-tailed test, 201
- On-line statistical process control, 12
 - and control charts, 268
- Operating characteristic (OC) curve
 - acceptance sampling, 469–473
 - attribute charts, 400–403
 - chain sampling plan, 501–503
 - control charts, 274–275
 - double sampling plan, 490–492
 - and producer/consumer risk, 472–473, 543
 - and reliability, 542–544
 - risk demonstrated with, 472–473
 - single sampling plan, 483–485
 - Type A OC curve, 470
 - Type B OC curve, 470
- Operator Quality Control period, 4
- Optimal quality level, 28–30
- Ord, J. K., 198, 227, 234, 261
- Ordinal scale, 158
- Organizational barriers, Deming's view, 67–68
- Original equipment manufacturer (OEM), 31, 128–129
 - core competencies, 31
- Orthogonal arrays, 629–639
 - hybrid orthogonal arrays, 638–639
 - and Latin square design, 629
 - and linear graphs, 629–639
- Orthogonal contrasts, 598–600
- Outliers, 160
- Out-of-control points, determination of cause, 284, 294–296
- Out-of-control processes, identification of, 280–282
- Paired samples
 - confidence interval for difference between two means, 195
- Parameter, statistical, 150
- Parameter design, Taguchi method, 615–617, 626, 644–646, 648–650
- Pareto diagrams, 120–121
 - steps in construction of, 120
 - use of, 120, 291
- Parry, P., 36, 45
- Patton, F., 48, 91
- p -chart, 372–384, 400–401
 - basic assumptions for, 384
 - construction of, 373–380
 - data sheet for, 374
 - with no standard specified, 374
 - process capability measurement, 444
 - with standard specified, 374–375
 - usefulness of, 373
 - and variable sample size, 380–383
- Pearn, W. L., 428, 464
- Performance, quality of, 11
- Performance evaluation
 - benchmarking, 111–114
 - Deming's view, 70–71, 74
 - quality auditing, 114–116
- Performance measures, for vendors, 116–118
- Performance standards, 100–102
 - components of, 100
 - six-sigma quality, 100–103
- Performance statistic, 625
- PERMIA method, 628
- Peterson, R. G., 560, 567, 612, 640, 663
- Philpot, J. W., 283, 288
- Plan stage, of Deming cycle, 63–64
- Point estimation, calculation of, 190
- Poisson distribution
 - approximation to binomial, 211–212
 - calculation of, 179–180
 - c -chart, 387–390, 402–403
 - cumulative, table for, 670–671
 - normal approximation to, 212–213
- Polansky, A. M., 240, 260
- Population
 - estimating parameters, 250–253
 - statistical, 150
- Population mean, calculation of, 159
- Population variance, calculation of, 162
- Posterior probability, 480–481
- Power of test, 203, 253, 254
- Precision, of data set, 158
- Precision-to-tolerance ratio, 434–435, 437
- Prevention costs, 23
- Pride of worker, Deming's view, 69–70
- Principal fraction, 608
- Prior probability, 480
- Probability, 150–156
 - additive law, 153
 - complementary events, 152
 - compound events, 151–152
 - independent events, 154
 - meaning of, 150
 - multiplicative law, 153–154
 - mutually exclusive events, 154, 156
 - relative frequency definition of, 150–151
 - simple events, 151
- Probability distributions, 173–188, 530–534
 - approximations for, 211–213
 - binomial distribution, 177–179
 - continuous distributions, 180–188
 - cumulative distribution function, 175
 - expected value, 175
 - exponential distribution, 184–186, 530–532
 - gamma distribution, 187–188
 - hypergeometric distribution, 176–177
 - log normal distribution, 188
 - normal distribution, 180–184
 - Poisson distribution, 179–180
 - probability density function, 173
 - probability distribution function, 173
 - Weibull distribution, 186–187, 532–534

- Probability limits, control charts, 269
- Probability plotting, 237–239, 443
 construction of, 237–239
 exponential plot, 239
 and Minitab, 237–239
 normal plot, 237–238
- Probability sampling, 53
- Process audit, 115
- Process capability, meaning of, 417
- Process capability analysis
 with attribute chart information, 444
 benefits of, 418–419
 Box-Cox transformation, use of, 444
 capability ratio (CR), 427–428
 identification of distribution, 442, 443–445
 with individual observations, 442
 nonlinear combinations, 452–453
 non-normal distributions, 443–445
 nonparametric approach, 444
 and specification limits, 420–422
 statistical tolerance limits, 420, 453–455
 and tolerance limits, 417–420
 with variable control chart information, 442
- Process capability, indices
 comparison of, 430–434
 confidence intervals on, 429
 C_p index, 423–424, 430–433
 C_{pk} index, 425–427, 430–433
 C_{pm} index, 428
 C_{pmk} index, 428–429
 C_{pq} index, 444–445
 hypothesis testing on, 429
 lower capability index, 424–425
 measurement error effects, 434–437
 and nonconformance rate, 441
 Taguchi capability index C_{pm} , 428, 430–434
 upper capability index, 424
- Process capability limits. *See* Natural tolerance limits
- Process capability ratio, 338
- Process costs, 25
- Process map, 122
- Process parameter, variable sampling plans for, 508–514
- Process spread
 meaning of, 416
 and specification limits, 420–422
- Producer's risk
 acceptance sampling, 468
 and OC curve, 472, 543
 single sampling plan, 484–490
- Product audit, 115
- Product improvement cycle, 59
- Productivity, relationship to quality, 33–34
- Proportion
 confidence interval, 195–196
 hypothesis testing, 207–209
- Public Law 100–107, 135
- p*-value, hypothesis testing, 203–204, 235, 236, 237, 238, 242, 243
- Quality
 attributes related to, 7, 8
 characteristics of, 8
 of conformance, 10
 defect, 9
 definition of, 7–8, 82
 of design, 9–10
 of performance, 11
 relationship to productivity, 33–34
 and reliability, 17–18
 standard, 9
 variables related to, 8
- Quality assurance, 13
 definition of, 13
- Quality audits, 114–116
 conformity quality audit, 115
 influencing factors, 115
 location/function-oriented audits, 116
 process audit, 115
 product audit, 115
 purposes of, 114
 suitability quality audit, 114
 system audit, 115
 usefulness of, 115–116
- Quality awareness, 76
- Quality breakthrough sequence, 79
- Quality circles
 history of, 6
 operation of, 14
- Quality control
 acceptance sampling plans, 12
 benefits of, 16
 evolution of, 4–7
 Juran's view, 80
 off-line quality control, 12
 statistical process control, 12
- Quality Control and Reliability Handbook H-108*, 544, 548
 failure-terminated test, 548–549
 time-terminated tests, 548–554
- Quality costs, 22–30
 appraisal costs, 23
 data requirements for, 24–25
 external failure costs, 24
 hidden failure costs, 24
 impact of quality improvement, 28–30
 improved productivity, impact of, 33
 internal failure costs, 23–24
 measurement of, 26–30
 prevention costs, 23
 quality cost report, 27
- Quality councils, 78
- Quality function deployment (QFD), 103–110
 effects of, 103, 109
 house of quality, 104, 107
 step in process, 104–110
- Quality improvement, 18–19
 Crosby's 14-step plan, 76–78

- Juran's view, 81–82
- Quality improvement teams, operation of, 14, 76
- Quality management, 30–32
 absolutes of, 76
 quality systems, 16–17
- Quality management grid, 77
- Quality measurement, function of, 76
- Quality philosophies
 comparison of philosophies, 82–85
 of Crosby, 75–78
 of Deming, 56–75
 of Juran, 78–82
- Quality planning
 Juran's view, 79–80
- Quality system, 17
- Quantile ratio, 241–242
- Quartile, 165–166, 232
- Quota system, Deming's view, 69
- Radial plot, 124–125
- Raghavarao, D., 560, 612, 629, 663
- Random effects model, 566
- Randomization, experimental design, 564–565
- Randomized block design, 572–577
 blocking, 572
 difference among treatment means, 574–577
F-statistic, 574–576
 pros/cons of, 573
 two-factor factorial experiment, 590–596
- Random numbers, uniform, table for, 686
- Randomness, of a sequence, 234–236
- Range, calculation of, 161–162
- Rational sample, control charts, 279, 292
- Ratio scale, 158–159
- R*-chart, 294–298
 analysis and \bar{X} -chart, 294
 control limits, 294, 298, 300
 Minitab construction, 296
 standardized values, 299
 variable sample size, 298
- Regression control chart. *See* Trend chart (regression control chart)
- Reinmuth, J. E., 189, 208, 227
- Rejection region, 202
- Reliability
 and complex systems, 539–540
 and components in parallel, 536–539
 and components in series, 534–536
 failure-terminated test, 544–548
 and life-cycle curve, 530
 and life testing plans, 544–554
 meaning of, 17, 529–530
 and operating characteristic curves, 542–544
 probability distributions, 530–534
 and quality, 17–18
 sequential life testing plan, 545
 standardized plans, 544
 and standby systems, 540–542
 system reliability, 534–542
 time-terminated test, 547, 548–554
- Replication, experimental design, 564
- Resnikoff, G. J., 515, 526
- Resolution III designs, 609
- Resolution IV designs, 610
- Resolution V designs, 610
- Response surface design, 649
- Response variable, in experiment, 560–561
- Robert Wood Johnson University Hospital
 Hamilton, case study, 139–141
 Malcolm Baldrige National Quality Award, 139
- Robustness, 613–614
- Romig, H. G., 5, 497, 526
- Roy, D. M., 131, 146
- Run charts, 235–236
 clustering, 235, 236
 mixture pattern, 235, 236
 oscillation, 235, 236
 patterns, 235–236
 random pattern, 235
 trend, 235, 236
- Ryan, T. P., 560, 663
- Sales base index, quality cost measure, 26
- Sample, statistical, 150
- Sample mean, calculation of, 159
- Sample size
 attribute charts, 371–372
 control charts, 279, 292, 294
 determination of, 250–254
 estimation in sampling, 250–254
- Sample space, 150
- Sample variance, calculation of, 162–163
- Sampling, 247–254
 advantages of, 248
 cluster sample, 249–250
 designs, 247
 element, 247
 errors in, 248
 estimation of sample size, 250–253
 frame, 247–248
 precision, 248
 proportional allocation, 249
 simple random sample, 248
 stratified sample, 248–249
 unit, 247
- Sampling distributions
 calculation of, 189–190
 Central Limit Theorem, 189–190
- Sampling frequency, control charts, 279–280, 292
- Sampling plans
 convenience sampling, 53
 function of, 497

- Sampling plans (*continued*)
 judgment sampling, 53
 100% sampling, 53
 probability sampling, 53
 for service business, 53
See also Acceptance sampling plan;
 Attribute sampling plan
- Sampling scheme, function of, 497
- Sampling system, function of, 497
- Sampling unit, in experiment, 561
- Scaled distance k , 426
- Scanlon, J., 5
- Scanlon Plan, 5
- Scatter diagrams, 123–124
 construction of, 123
 use of, 123
- s -chart, 311–315
- Schmidt, S. R., 628, 663
- Screening design, 649
- Sensory quality, 8
- Sequential life testing plan, 545
- Sequential sampling plan, 503–504
 item-by-item sampling, 503
- Service industries, 136
 control chart applications, 343, 393, 395–396
 effectiveness/efficiency factors, 50
 compared to manufacturing industries,
 48–49
 quality characteristics, 50–52
 quality measures, 52
 quality monitoring methods, 52–53
 quality service model, 53–56
- Shapiro, S. S., 242, 261, 423, 464
- Shewhart control charts. *See* Control charts
- Shewhart cycle, 63
- Shewhart, W. A., 5, 63, 265
- Shoemaker, A. C., 628, 663
- Signal-to-noise ratio (S/N), 615, 624–628
 evaluation of, 627–628
 and larger values, 627
 PERMIA method, 628
 relationship of variance to mean, 624–626
 and smaller values, 627
- Simple events, probability, 151–152
- Simple random sample, 248
- Single-blind study, 566
- Single sampling plan
 acceptance sampling, 473
 attribute sampling, 483–490
 OC curve for, 483–484
 and risk factors, 484–490
- Six-sigma quality, 100–103
 analyze phase, 103
 control phase, 103
 define phase, 102
 features of, 100–102
 improve phase, 103
 measure phase, 102
- Skewness coefficient, 166
 calculation of, 169
- Slifker, J. F., 242, 261
- Special causes, nature of, 18, 84, 267
- Specification, meaning of, 9
- Specification limits, 9
 compared to control limits, 416–417
 definition of, 416
 and process capability analysis, 420–422
 compared to tolerance limits, 416
- Spider chart, 111–112
- Sporadic problems, 84
- Standard, meaning of, 9
- Standard deviation
 calculation of, 163–165
 control charts for, 310–315
- Standardized control charts, 298–299
- Standardized reliability plans, 544
- Standardized sampling plan, 497–501, 518–519
 acceptable quality levels (AQL), 497, 518
 standards for, 497–498, 518
- Standard normal distribution, table for, 672–674
- Star plot, 124–125
- Statistic, meaning of, 150
- Statistical control, 302
 meaning of, 267
- Statistical process control (SPC)
 control charts, 265–266, 268
 data collection, 279–280
 meaning of, 12, 267–268
 on-line, 12, 268
- Statistical Quality Control period, 5
- Statistical tolerance limits, 420, 453–455
 based on normal distribution, 453–454
 meaning of, 420
 nonparametric, 454–455
- Statistics
 analysis of variance (ANOVA), 567–572
 data collection, 156–157
 descriptive statistics, 156–172
 inferential statistics, 156, 188–210
 kurtosis coefficient, 167–169
 measurement scales, 158–159
 measures of association, 169–171
 measures of central tendency, 159–161
 measures of dispersion, 161–166
 parameter, 150
 population, 150
 probability, 150–156
 probability distribution approximations, 211–213
 probability distributions, 173–188
 sample, 150
 sampling, 247–254
 skewness coefficient, 166
See also Inferential statistics
- Steering arm, 81

- Stem-and-leaf plots, 231–232
- Stephens, K. S., 311, 367, 400, 414, 560, 663
- Stephens, M. A., 237, 261
- Strategic quality management, Juran's view, 79–80
- Stratification patterns, control charts, 308–309
- Stratified random sample, 248–249
- Structural characteristics, of quality, 8
- Stuart, A., 198, 227, 234, 261
- Subassemblies, tolerances on, 446–448
- Suitability quality audit, 114
- Supervisors, training of, 78
- Supplier relationship management, 31–32
- Supply chain management, 30–32
- System audit, 115
- System design, Taguchi method, 615, 644, 645
- System of Profound Knowledge, 56–57
- System reliability, 534–542
- Systems approach, quality, 17

- Taguchi capability index C_{pm} , 428, 430–434
- Taguchi, Genichi, 65, 428, 464, 613, 629, 634, 663
- Taguchi method, 613–650
 - attribute data, use of, 646–648
 - concept of quality, 613–614
 - critique of, 627–628, 648–650
 - estimation of effects, 639–644
 - linear graphs, 629–639
 - loss functions, 617–624
 - manufacturing tolerances, determination of, 620–621
 - orthogonal arrays, 629–639
 - parameter design, 615–617, 626, 644–646, 648–649
 - purpose of, 613–614
 - signal-to-noise ratio (S/N), 615, 624–628
 - system design, 615, 644–645
 - tolerance design, 617, 645
- Target value, 614–615
- t -distribution, 192–193
 - t , values for right-tail area, 675–676
- Test statistic, hypothesis testing, 199
- The Bama Companies, Inc., 37–39
- Three-dimensional plot, 127
- 3M Company, vendor certification, 119
- Time-based competition, and benchmarking, 114
- Time-oriented characteristics of quality, 8
 - timeliness and service industries, 50–51
- Time-terminated test, 545, 547
 - with *Handbook H-108*, 548–554
- TL 9000 Standard*, 134
- Tobarska, B., 513, 526
- Tolerance design, Taguchi method, 617, 645
- Tolerance limits, 419–420, 453–455
 - on assemblies and subassemblies, 446–448
 - definition of, 416
 - on individual components, 448–449
 - on mating parts, 449–451
 - natural tolerance limits, 419–420
 - nonparametric statistical tolerance limits, 454–455
 - statistical tolerance limits, 420, 453–455
 - upper and lower tolerance limits, 416
- Total Quality Control Organizationwide phase, 6
- Total Quality Control period, 5
- Total quality management (TQM), 94–96
 - basic values in, 94–95
 - company vision, 96
 - examples of practitioners, 97
 - features of, 94
- Total quality system, definition of, 6
- Training
 - Deming's view, 66, 72
 - supervisory, 78
- Transformations, to achieve normality, 239–244
 - Johnson transformation, 240–244
 - power transformation, 240, 241
- Transition fits, 450–451
- Treatment, in experiment, 560
- Trend chart (regression control chart), 335–338
 - construction of, 336–337
- Trending patterns, control charts, 306
- Trimmed mean, calculation of, 161
- Tsui, K. L., 648, 663
- Tukey, J. W., 234, 261
- Tukey, P. A., 232, 260
- 2^k factorial experiment, 602–613
 - confounding in, 606–607
 - design resolution, 609–610
 - factorial set of treatments, list of, 602
 - fractional replication in, 607–613
 - half-fraction of, 608–609
 - 2^{k-p} fractional factorial experiment, 610–613
- Two-tailed test, 201
- Type A operating characteristic curve, 470
- Type B operating characteristic curve, 470
- Type I errors
 - acceptance sampling (producer's risk), 468
 - and control charts, 271, 282, 400
 - hypothesis testing, 202
 - and sample size, 250–254
- Type II errors
 - acceptance sampling (consumer's risk), 468–469
 - and control charts, 271–273, 400–403
 - hypothesis testing, 202–203
 - and sample size, 253–254

- U -chart, 393–396
 - construction of, 394–396
 - process capability measurement, 444
- u -chart, 390–393
 - process capability measurement, 444
 - with variable sample size, 391–392
- Unbalanced experiment, 567
- Unit base index, quality cost measure, 27
- Upper capability index, 424
- Upper control limit, control charts, 266
- Upper natural tolerance limits, 419–420

- Upper tolerance limits, 416
- U.S. Department of Commerce, 9, 37, 45, 135, 146
- U.S. Department of Defense, 544, 558
- U.S. Food, Drug, and Cosmetic Act, 5
- Variables
 - continuous, 157
 - discrete, 157
 - experimental design, 561–564
 - of quality, 8
- Variable sampling, 507–519
- Variable sampling plans
 - advantages/disadvantages of, 507–508
 - for estimation of lot proportion non-conforming, 514–518
 - Forms 1 and 2, 515, 517
 - process average estimation methods, 508–514
 - for process parameter, 508–514
- Variance
 - calculation of, 162–165
 - confidence interval, 196–198
 - hypothesis testing, 209–210
 - population variance, 162
 - sample variance, 162–163
- Vendor certification, 118–120
 - example programs, 119
 - quality levels, 119–120
- Vendors, 116–120
 - performance measurement of, 117–118
 - selection of, 61–62
- Vision of company, and total quality management (TQM), 96
- V-mask parameters, cumulative sum chart (cusum charts), 324–327
- Wadsworth, H. M., 311, 367, 400, 414, 560, 663
- Wald, A., 503, 526
- Walker, E., 283, 288
- Warning limits, control charts, 276
- Wasserman, W., 170, 227
- Wear-out phase, 530
- Weibull distribution
 - calculation of, 186–187
 - failure-rate function, 532–534
 - mean time to failure, 532–533
 - for model failure rate, 532–534
- Welch, T. E., 36, 45
- Whiskers, 232
- Wild patterns, control charts, 307–308
- Willig, J. T., 36, 45
- Wilson, K. B., 560, 649, 662
- Woodall, W. H., 321, 367
- Work standards, Deming's view, 69
- Wu, Y., 613, 663
- \bar{X} -chart, 293–310
 - control limits, 293–294, 299–300
 - interpretation of, 302–303
 - Minitab construction, 296–297
 - standardized values, 298–299
 - steps in construction of, 293–296
 - variable sample size, 298
- Xerox Corporation
 - benchmarking, 112
 - and total quality management (TQM), 97
- Xie, M., 398, 414
- Zeithaml, V. A., 48, 91
- Zero defects
 - history of, 6
 - and tolerance limits, 101
- Zero defects program (ZD)
 - ad hoc committee for, 78
- Zero defects (ZD) day, 78