

Index

• Numerics •

2^k factorial experiments
analysis, 207–215
ANOVA (analysis of variance), 216
blocking in, 206
curvature, 216
design matrix, 204–205
equation general form, 214
experimental codes, 204–205
factor selection, 202–203
fractional factorial experiments, 216
interaction effects, 210–211
level setting, 203–204
main effects, 207–209
randomization, 206
replications, 216
robustness, 216
RSM (response surface methods) and optimization, 216
Xs, 203
80-20 rule, 39–40
3-Cs Explorer, 280
 Σ (sigma), sums in equations, 89

• A •

accountability, managerial perspective and, 13
accuracy in measurement, 155–156, 277
adjusted short-term capability index, 145–146
affinity diagram, business case writer and, 70
ALN (asynchronous learning network), 300
alpha risk, 173
analyze (DMAIC Analyze phase)
description, 42
project responsibilities and, 66
ANOVA (analysis of variance)
 2^k factorial experiments, 216
statistical analysis, 267, 271
architecture of software, 280–282
as-is state, modeling, 255
ASA (American Statistical Association), 314
ASQ (American Society of Quality), 314
assignable cause variation, 100

associations, 314
asynchronous mentored learning, 300
attainable (RUMBA), 126
attribute data, 150–151
attribute data control charts
defectives, 235
introduction, 221
 p charts, 235, 237–238
 u charts, 235, 238–239
attribute measurement system studies,
158–160
audit plan, data collection, 266
audits, MSA and, 156–158
autocorrelation, statistical analysis, 271
average. *See* mean

• B •

Bank of America, Six Sigma and, 12
basic stats, statistical analysis tool, 267
behavior charts, 117
believable (RUMBA), 126
belts, 71. *See also* Green Belt; Yellow Belt
benchmarks, stretch goals, 304
benefits, project definition and, 292
best fit, regression and, 275
best practices, 303–307
between/within analysis, process capability
analysis, 274
binomial analysis, process capability
analysis, 274
Black Belt
characteristics, 53
description, 51
initiative roles, 55
manager tools and, 285
Master Black Belt, 52
blocking in experiments, 206
boil-the-ocean experiments, 200–201
box and whisker plots, 108–111
exploratory analysis and, 276
statistical analysis, 269
BPA (business process analysis) software, 279
BPM (business process management)
software, 279

- BPMN (business process modeling notation), 252
- breakthrough
- designing for, 44–45
 - improvement, 80
 - leverage for, 52
 - managing for, 45
 - processing for, 44
 - thinking for, 43–44
- breakthrough equation ($Y = f(X) + \epsilon$), 27–29
- bullhorn, as tools, 288
- business case writer
- exercise, 70–71
 - projects and, 69–71
- business metrics, managerial perspective and, 14
- business unit leaders, core team, 49
- C •
- capability. *See also* CCA (capability-complexity analysis)
- improvement plan, 147–148
 - indices, 144–147
 - introduction, 123
 - KISS and, 262–263
 - yield, 128–133
- capability and complexity analysis, process
- optimization tool, overview, 246
- capability six-pack, process capability analysis, 274
- casting a big net, 162–163
- category data, 150–151
- causation
- connections, 32
 - correlation and, 31–32
- cause and effect, inputs, 29
- CBT (computer-based training), 299–300
- CCA (capability-complexity analysis), 263
- CDF (cumulative distribution function) plots, statistical analysis, 269
- C&E (cause-and-effect) matrix, process
- optimization tool
 - fishbone chart and, 258–259
 - overview, 246
- celebration, best practices and, 306
- central limit theorem
- introduction, 170
 - sampling distribution and, 171
- Champions
- characteristics, 48
 - deployment and, 57
 - project definition and, 71
 - tools and, 285
- change, managerial perspective and, 15–16
- characteristic charts
- creating, 118
 - runs, 120
 - shifts, 121
 - trends, 120
 - variation beyond expected limits, 119–120
- characterizing experiments, 201
- CLs (control limits)
- histograms and, 224
 - probability and, 224
- coaching, Black Belts and, 53
- coded design matrix, 2^k factorial experiments, 205
- coincidence, correlation and, 32
- Collins, Jim (*Good to Great*), 11
- commitment, managerial perspective and, 13
- common cause variation, processes and, 225
- common-cause variation, 34, 97
- communication and leadership tools, 286–288
- communications, plan, initialization and, 56
- communications representative, core team, 49, 50
- compensation plans, change and, 15
- competency models, change and, 15
- conditions, experiments, 197
- conferences, 314–315
- confidence intervals
- averages, 174–175
 - χ^2 , 176–177
 - differences between items, 174–176
 - introduction, 172
 - mean and, 172–176
 - proportions, 178–180
 - risk, 173
 - standard deviation, 176–178
 - summary table, 178–180
 - t values, 174
 - variation, 177–178
- confounding, correlation and, 32
- consultants, 317
- continuous control charts
- $\bar{X} - R$ (averages and ranges) chart, 231, 234
 - $\bar{X} - S$ (averages and standard deviation) chart, 235

- I*–*MR* (individual and moving range) chart, 231, 232–233
 - pairs, 231
 - SPC, 230
 - continuous data, 151–152
 - continuous data control charts, 221
 - continuous variable measurement system studies, 160–161
 - control chart, SPC
 - attribute data control charts, 221, 235–239
 - attributes, 223
 - continuous data control charts, 221
 - control limits, 223
 - data collection, 229–230
 - distribution, 222
 - drifts and, 227
 - LCL (lower control limit), 223
 - limits, 226
 - patterns and, 227
 - rational subgroups, 230
 - sample data, 226
 - shifts and, 227
 - subgroup data, 226
 - trending, 222
 - UCL (upper control limit), 223
 - zones, 227
 - control limits. *See* CLs (control limits)
 - Control phase, 42, 66
 - emphasis on, 217
 - plan aspects, 218
 - process control of inputs, 218
 - process control plan, 219–221
 - process monitoring of outputs, 218
 - control plan
 - data collection, 266
 - projects, 65
 - core team
 - characteristics, 49
 - description, 48–49
 - members, 49
 - correlation
 - causation and, 31–32
 - description, 30–32
 - relationships, 180–183
 - scatter plots, 113
 - superstitious delusions, 31–32
 - correlation coefficient, calculating, 182
 - cross-correlation, statistical analysis, 271
 - CT (critical to) tree, 245, 249
 - CTQs (critical-to-quality outputs)
 - continuous control charts, 230
 - process management summary and, 219
 - CTXs (critical-to-X characteristics)
 - distributions and, 88
 - introduction, 17
 - performance, 18–19
 - statistics and, 85
 - culture change, managerial perspective and, 16
 - curvature, 2^k factorial experiments, 216
 - curve fitting
 - multiple linear regression, 193–194
 - relationships and, 183–194
 - customers
 - manager tools and, 286
 - managerial perspective and, 13
- D •
- 3D scatter plots, statistical analysis, 269
 - data, best practices and, 305
 - data collection, control charts, 229–230
 - data collection plan
 - audit plan, 266
 - control plan, 266
 - format, 265
 - sources, 265
 - stability, 265
 - timing, 265
 - transfer, 265
 - data types
 - attribute data, 150–151
 - category data, 150–151
 - continuous data, 151–152
 - ordinal data, 151
 - rank order, 151
 - variable data, 151–152
 - decomposition, time-series analysis, 270
 - defect rate
 - DPMO (defects per million opportunities), 134–137
 - DPO (defects per opportunity), 134–137
 - DPU (defects per ubiquitous unit), 134
 - failure and, 133–134
 - metrics summary, 137
 - Poka-Yoke, 239
 - yield and, 138
 - defectives, attribute data control charts, 235–239

- Define phase
 - description, 42
 - focus, 63
 - project responsibilities and, 66
 - deployment
 - Champion selection, 57
 - expansion and, 58
 - initialization and, 56
 - sustain phase, 59
 - deployment leader
 - core team, 49
 - responsibilities, 47
 - tools and, 285
 - Design FMEA, 260
 - design matrix, 2^k factorial experiments, 204–205
 - designing domain
 - description, 43
 - designing for breakthrough, 44–45
 - DFSS (Design for Six Sigma), 44–45
 - determinism
 - breakthrough equation and, 28
 - proactivity, 31
 - deviation, variation spread and, 95
 - DFM (design for manufacturability), 271
 - DFSS (Design for Six Sigma), design and, 44–45
 - distribution (statistics)
 - control charts, 222
 - CTXs and, 88
 - definition, 88
 - degree of dispersion, 92
 - mode, 89
 - object statements and, 88
 - range, 91–92
 - sampling distribution, 171
 - squaring, 93
 - SSE (summed squared error), 93
 - variance, 94
 - DMAIC (Define-Measure-Analyze-Improve-Control)
 - analyze, 42
 - control, 42
 - define, 42
 - improve, 42
 - improvement methodology, 42
 - introduction, 41
 - measure, 42
 - recognize, 43
 - tollgates, 42
 - DOE (Design of Experiments), statistical analysis
 - factorial designs, 273
 - introduction, 267
 - response surface designs, 273
 - steps, 272–273
 - Taguchi designs, 273
 - domains of activity
 - designing, 43
 - managing, 43
 - processing, 43
 - thinking, 43
 - dot plots
 - creating, 103–104
 - interpreting, 104–108
 - statistical analysis, 269
 - variation mode, 104–107
 - variation shape, 104
 - DPMO (defects per million opportunities), 134–137
 - DPO (defects per opportunity), 134–137
 - DPU (defects per ubiquitous unit), 134
 - drifts, control charts, detecting, 227
 - Dupont, Six Sigma and, 12
- **E** ●
- e-learning Six Sigma, 299–300
 - e-mail presentations, 287
 - enterprise platforms for software, 281–282
 - entitlement level
 - definition, 101
 - processing for breakthrough, 44
 - equation. *See* breakthrough equation
 - errors, Poka-Yoke, 101
 - Excel, 279
 - executive representatives
 - core team, 49
 - tools and, 285
 - expansion, deployment and, 58
 - expectation, variation and, 33
 - experiments
 - analysis, 207–215
 - ANOVA (analysis of variance), 216
 - blocking, 206
 - boil-the-ocean experiments, 200–201
 - characterizing, 201
 - codes, 204–205
 - conditions, 197

curvature, 216
 fractional factorial experiments, 216
 inputs, 197
 interaction effects, 210–211
 introduction, 195–196
 2^k factorial experiments, 202–215
 levels, 197
 main effects, 207–209
 observational studies and, 196
 one-factor-at-a-time approach, 199
 optimization, 201
 Pareto Principle and, 203
 Plackett-Burman designs, 203
 planning, 200
 progressive, iterative approach, 201–202
 purpose, 196
 randomization, 206
 replications, 197, 216
 response and, 197
 robustness, 216
 RSM (response surface methods) and
 optimization, 216
 runs, 197
 runs, minimizing number, 200
 screening, 201
 significant effects, 212–214
 Six Sigma approach, 200
 super-experiments, 200–201
 trial-and-error approach, 198–199
 variables, 197
 variables, multiple, 200
 Xs and, 196
 Y, 198
 exploratory analysis, statistical analysis,
 268, 276
 exponential smoothing, statistical
 analysis, 271

● F ●

face-to-face communication, tools, 287
 factorial designs, DOE, 273
 factors, 2^k factorial experiments
 levels, setting, 203–204
 selecting, 202–203
 failure, defects and, 133–134
 fat pencil test, scatter plots, 115
 finance representative
 core team, 49, 50
 tools and, 285

finances guidelines, initialization, 56
 fishbone diagram process optimization tool
 C&E and, 259
 overview, 246
 fitted line, regression and, 275
 FMEA (failure mode effects analysis) process
 optimization tool
 applications, 260
 likelihood of detection, 261
 overview, 246
 probability of occurrence, 261
 severity of impact, 261
 forecasting, time-series analysis, 270
 formal presentations, tools, 287
 format, data collection, 265
 fractional factorials, 2^k factorial experiments,
 203, 216
 FTY (first time yield), 129–130
 functional representatives
 core team, 49
 project definition and, 71
 functional sub-optimization, software, 281
 funnel analogy, measurement, 161–163
 funnel reports, 264

● G ●

gauge variable measurement system studies,
 160–161
 General Electric, Six Sigma and, 12
 goals
 best practices and, 306
 stretch goals, 303–304
Good to Great, 11
 grade, quality comparison, 17
 graphical analysis, observational studies and,
 165–167
 Green Belt
 characteristics, 53
 description, 51
 initiative roles, 55
 manager tools and, 285
 training, 52

● H ●

hard savings, 76
 hidden factory, 21, 130–131
 hierarchy of roles, 52

histograms

- control limits and, 224
- creating, 103–104
- interpreting, 104–108
- multi-modal, 106
- statistical analysis, 269
- variation mode, 104–107
- variation shape, 104

history of Six Sigma, 15

Honeywell, Six Sigma and, 12

human resources, guidelines, initialization and, 56

human resources representative, core team, 49, 50

• *I* •*I*–*MR* (individual and moving range) chart, 231, 232–233

iGrafx, 280

implementation, successes, 57

impromptu presentations, tools, 287

improve phase

- breakthrough improvement, 80
- description, 42
- how much, 78–80
- project responsibilities, 66

information technology representative

- core team, 49, 50

- initialization, 56

initialization

- communications plan, 56
- deployment process and, 56
- elements, 56
- finance guidelines, 56
- HR guidelines, 56
- information technology and, 56
- launch planning, 56
- management dashboard, 56
- project reporting, 56
- project selection, 56
- project tracking, 56

initiatives

- lifecycle, 55–59
- overview, 46–47
- stages, 55

inputs

- cause and effect, 29
- experiments, 197
- measurement and, 36

interaction effects

- experiments, 210–211
- multiple linear regression, 193

interaction effects plots, observational studies and, 167

interval plots, statistical analysis, 269

IQPC (International Quality and Productivity Center), 315

ISSSP (International Society of Six Sigma Professionals), 314

iterative approach to experiments, 201–202
Ixpersion, 315• *J* •

JMP, 279

job roles, change and, 15

• *K* •

key executive representatives, core team, 49

KISS, capability-complexity and, 262–263

KM (knowledge management) tools, 298

knowledge management tools, 286

• *L* •

launch

- planning, initialization and, 56
- process, 83–84

LCL (lower control limit), 223

leadership

- hierarchy of roles, 54
- managing for breakthrough and, 45

leadership system, change and, 15

learning tools, 286

least squares, regression and, 275

letter values, exploratory analysis and, 276

letters, as tools, 288

levels

- experiments, 197
- factors, experiments, 203–204

leverage, overview, 38–40

line fitting, relationships and, 191–192

Linux platforms for software, 281

logistics, regression and, 275

long-term capability indices, 146–147

long-term sigma score, 140–141
 long-term variation. *See* LT (long-term variation)
 Lord Kelvin, 36
 LSL (lower specification limit), 125
 LT (long-term variation)
 formulas, 100
 introduction, 35
 overview, 99–101
 ST (short-term) variation, 102

• M •

Macintosh platforms for software, 281
 main effects, experiments, 207–209
 main effects plots
 multiple linear regression, 193
 observational studies and, 167
 management dashboard, initialization and, 56
 management tools
 Black Belts, 285
 Champions, 285
 communication and leadership tools, 286
 communications, 287–288
 customers, 286
 deployment leaders, 285
 executive management, 285
 financial executives, 285
 Green Belts, 285
 introduction, 283
 knowledge management tools, 286
 learning tools, 286
 Process Owners, 285
 project management, 286, 288–295
 reporting tools, 286
 suppliers, 285
 Yellow Belts, 285
 managerial perspective of Six Sigma
 accountability and, 13
 change and, 15–16
 commitment and, 13
 connected business metrics and, 14
 customers and, 13
 introduction, 11
 process orientation, 14
 project focus, 14
 ROI (return on investment), 13
 science and leadership bridge, 12–13
 successful companies, 12
 technology and, 14
 tools, 14
 VOC (voice of the customer) and, 13
 managing domain, 43, 45
 marginal plots, statistical analysis, 270
 Master Black Belt. *See* MBB
 matrix plots, statistical analysis, 269
 MBB (Master Black Belts), overview, 52–53
 mean
 calculating, 89–90
 confidence intervals, 172–176, 174–175
 time-series analysis, 270
 variation and, 33, 89
 variation location and, 91
 measurable (RUMBA), 126
 Measure phase
 description, 42
 project responsibilities and, 66
 measurement
 confidence, 171
 funnel analogy, 161–163
 Lord Kelvin and, 36
 observational studies, 163–165
 output values, 88
 pitfalls, 311
 statistics and, 87–88
 variation, 87
 variation, location, 88–91
 visual inspection, 157–158
 measurement system
 accuracy, 154–155
 attribute measurement system studies, 158–160
 capability analysis, 152–161
 continuous variable measurement system studies, 160–161
 gauge variable measurement system studies, 160–161
 graphical analysis, 165–167
 MSA, 156–161
 precision, 155–156
 precision, repeatability, 155
 precision, reproducibility, 155
 resolution, 154
 variation sources, 154–156
 measurement systems analysis, statistical analysis, 268, 276–278
 median, 90, 91
 median polish, exploratory analysis and, 276
 memos, as tools, 288
 mentoring, Black Belts and, 53
 methodology, applications, 13

metrics summaries
 defect rate, 137
 yield, 133
 Minitab, 279
 mistake-proofing. *See* Poka-Yoke
 mode
 distribution and, 89
 variation location and, 91
 modeling, process optimization tool
 as-is state, 255
 baseline setting, 255
 BPMN (business process modeling notation), 252
 closed-loop behavior simulation, 255
 overview, 245
 process maps, 251
 process maps, drawing, 252–253
 process points, 253–254
 process setting, 255
 SIPOC and, 255
 swim lanes, 254
 to-be state, 255
 Motorola, Six Sigma and, 12
 moving averages, time-series analysis, 270
 MSA (measurement system analysis), audits, 156–158
 multi-modal histograms
 definition, 106
 outliers, 107
 variation average, 107
 variation range, 107
 multi-variable analysis, process capability analysis, 274
 multi-variable studies, observational studies and, 167
 multiple linear regression, 184, 193–194
 multivariate analysis, statistical analysis, 268, 275–276

• N •

n , data sets in equations, 89
 needs assessment
 project focus and, 66–67
 strategies, 67–68
 VOB (voice of the business) and, 68
 VOC (voice of the customer) and, 68

non-normal analysis, process capability analysis, 274
 normal analysis, process capability analysis, 274

• O •

objective statements
 distributions and, 88
 overview, 80
 writing, 82–83
 objectives, project definition and, 292
 observational studies
 description, 163–165
 experiments and, 196
 graphical analysis and, 165–167
 interaction effects plots, 167
 main effects plots, 167
 multi-variable studies, 167
 obsession, variation obsession, 33
 one-factor-at-a-time approach to experiments, 199
 one-sided specifications, 124
 operation cycle time, process maps, 253
 opportunities, 135, 312
 optimization experiments, 201, 216
 ordinal data, 151
 outcome
 determining, 304
 measurement and, 36
 outliers
 multi-modal histograms, 107
 variation, 90
 output, continuous control charts, 230
 output values, statistics and, 88
 output variation, special cause factors, 100
 overall effect, multiple linear regression, 193

• P •

p charts (attribute data), 235, 237–238
 pairing continuous control charts, 231
 Pareto diagrams
 experiments and, 203
 measurement systems and, 158
 RPN (risk priority number), 262
 statistical analysis, 269
 partial least squares, regression and, 275
 patterns in control charts, detecting, 227

- PC-Windows, 280–281
- performance, CTX, 18–19
- periodicals, 316
- phone calls as tools, 288
- pitfalls, 309–312
- Plackett-Burman experiment designs, 203
- planning experiments, 200
- plans, process optimization tool, overview, 246
- platforms and protocols, software, 278–280
- plots and charts, statistical analysis tool
 - box and whisker plots, 108–111, 269
 - CDF plots, 269
 - 3D scatter plots, 269
 - dot plots, 103, 269
 - histograms, 103, 269
 - interval plots, 269
 - introduction, 267
 - matrix plots, 269
 - Pareto charts, 269
 - scatter plots, 111–113, 269
- Poisson analysis, process capability analysis, 274
- Poka-Yoke
 - errors and, 101
 - examples, 261
 - overview, 239
 - transactional processes and, 240
 - Type-1 corrective action and, 240
 - Type-2 corrective action and, 240
- practical solution, projects, 65
- precision in measurement, 155–156, 277
- probability density function (statistics), 88
- probability distribution (statistics), 88
- probability plots, statistical analysis, 270
- problem statements
 - examples, 77–78
 - introduction, 76
 - structure, 76
- problems
 - improvements, 78–80
 - objective statements, 80, 82–83
 - themes, 68
 - transformation, 65
- process behavior charts
 - creating, 118
 - runs, 120
 - shifts, 121
 - trends, 120
 - variation beyond expected limits, 119–120
- process capability analysis, statistical analysis
 - between/within analysis, 274
 - binomial analysis, 274
 - capability six-pack, 274
 - introduction, 267
 - multi-variable analysis, 274
 - non-normal analysis, 274
 - normal analysis, 274
 - Poisson analysis, 274
 - VOC (voice of the customer) and, 273
 - VOP (voice of the process) and, 273
- process control plan
 - administrative section, 220
 - introduction, 219
 - method of control, 220
 - SOPs, 220–221
 - Type-1 corrective action, 240
 - Type-2 corrective action, 240
- process FMEA, 260
- process leaders, project definition and, 71
- process management summary, 219
- process maps
 - BPMN (business process modeling notation), 252
 - costs, 254
 - drawing, 252–253
 - process points, 253–254
 - value added, 254
- process modeling. *See* modeling, process optimization tool
- process optimization tools
 - capability and complexity analysis, 246
 - C&E (cause-and-effect) matrix, 246
 - CT (critical to) tree, 245, 248–251
 - description, 244
 - fishbone diagram, 246
 - FMEA (failure mode effects analysis), 246
 - modeling, 245, 251–255
 - plans, 246
 - simulation, 246, 256–257
 - SIPOC (Suppliers-Input-Process-Outputs-Customers), 245
 - software, 279–280
- process orientation
 - managerial perspective and, 14
 - processing for breakthrough, 44
- Process Owners, tools and, 285
- process problems, Green Belts, 53

- processes
 - common cause variation and, 225
 - in control, 226
 - control of inputs, 218
 - description, 218
 - monitoring of outputs, 218
 - special-cause variation, 225, 228
 - stable, 226
 - tampering with the process, 218
 - transactional, Poka-Yoke and, 240
 - processing domain, 43
 - product FMEA, 260
 - products, quality, 17–20
 - professional societies, 314
 - progressive approach to experiments, 201–202
 - project definition
 - elements, 292
 - improvements, 72–73
 - mistakes, 71
 - persons involved, 71
 - steps in process, 72
 - worksheet, 73
 - project focus
 - characteristics, 64
 - managerial perspective and, 14
 - needs assessment and, 66–67
 - project management tools
 - definition, 289–290, 291–292
 - description, 286
 - ideation, 289–290
 - reporting, 295–297
 - selection, 290–291
 - tracking, 293–295
 - project reporting, initialization and, 56
 - project selection
 - change and, 16
 - guidelines, initialization, 56
 - project tracking, initialization and, 56
 - projects
 - business case writer function, 69–71
 - characteristics, 64
 - launching, 83–84
 - life cycle, 64–65
 - problem themes, 68
 - problem transformation, 65
 - responsibilities of those involved, 65–66
 - savings, 76
 - strategies, 67–68
 - proportions, confidence intervals, 178–180
 - publications, 315
 - purpose, project definition and, 292
- *Q* •
 - quality
 - grade comparison, 17
 - technical perspective and, 17–20
 - *R* •
 - $\bar{X} - R$ (averages and ranges) chart, 231, 234
 - randomization in experiments, 206
 - range of distribution
 - definition, 91–92
 - variation spread and, 95
 - rank order data, 151
 - rational subgroups, control charts, 230
 - RDMAIC, 43
 - reasonable (RUMBA), 126
 - Recognize phase, 43
 - regression, statistical analysis, 268, 275
 - relationships
 - correlation, 180–183
 - curve fitting, 183–194
 - fitting lines, 191–192
 - multiple linear regression, 184
 - residuals, 186–187
 - scatter plots, 180–181
 - simple linear regression, 184
 - reliability and survivability, statistical analysis, 268, 278
 - repeatability of precision in measurement, 155
 - replications
 - experiments, 197
 - 2^k factorial experiments, 216
 - reporting
 - funnel reports, 264
 - project management tools and, 295–297
 - simulations, 257
 - tools, 286
 - reproducibility of precision in measurement, 155
 - residuals, 186–187, 189
 - resistant line, exploratory analysis and, 276
 - resistant smoothing, exploratory analysis and, 276
 - resolution, measurement, 154
 - resources
 - associations, 314
 - colleagues, 313
 - conferences, 314–315

- consultants, 317
 - periodicals, 316
 - process maps, 253
 - professional societies, 314
 - publications, 315
 - Six Sigma corporations, 314
 - symposia, 314–315
 - technology vendors, 317
 - Web portals, 316
 - response, experiments and, 197
 - response surface designs, DOE, 273
 - results
 - process simulations, 257
 - projects, 65
 - targeting, 304
 - rise to run, line slope, 116
 - risk
 - alpha risk, 173
 - confidence intervals, 173
 - risk and controls, project definition and, 292
 - robustness, 2^k factorial experiments, 216
 - ROI (return on investment), value and, 13
 - Rootogram, exploratory analysis and, 276
 - RPN (risk priority number)
 - FMEA (failure effects mode analysis) and, 261–262
 - Pareto charts, 262
 - RSM (response surface methods), 2^k factorial experiments, 216
 - RSS (Royal Statistical Society), 314
 - RTY (rolled throughput yield), 131–133
 - RUMBA, 125
 - runs, experiments, 197, 200
- S ●
- $\bar{X} - S$ (averages and standard deviations)
 - chart, 231, 235
 - sample data, control charts, 226
 - sampling distribution, 171
 - savings
 - hard savings, 76
 - soft savings, 76
 - scatter plots
 - correlation amount, 113
 - correlation direction, 115
 - creating, 111–113
 - fat pencil test, 115
 - relationships, 180–181
 - slope of line, 116–117
 - statistical analysis, 269
 - strength of effect, 115
 - schedule, project definition and, 292
 - science and leadership, managerial perspective, 12–13
 - screening
 - experiments, 201
 - measurement and, 157–158
 - second-order effects, multiple linear regression, 193
 - self-healing culture, sustain phase, 59
 - service, quality, 17–20
 - shared repositories, as tools, 288
 - shifts, control charts, detecting, 227
 - short-term capability index, 144–145
 - short-term sigma score, 140–141
 - short-term variation. *See* ST (short-term variation)
 - sigma scale, 23–24
 - sigma shift, 141–143
 - Sigma (Z) score
 - changing, 140
 - deviations, 138–140
 - score table, 142–143
 - short-term vs. long-term, 140–141
 - sigma shift, 141–143
 - SigmaFlow, 280
 - simple linear regression, 184
 - simulation, process optimization tool
 - configuration, 256–257
 - overview, 246
 - reports, 257
 - results, 257
 - simulation environment, 256
 - SIPOC (Suppliers-Input-Process-Outputs-Customers), 245
 - developing, 247–248
 - process modeling and, 255
 - VOC (voice of the customer) and, 248
 - Six Sigma
 - Bank of America and, 12
 - breakthrough equation, 27–29
 - description, 9
 - Dupont and, 12
 - General Electric and, 12
 - history, 15
 - Honeywell and, 12
 - management system orientation, 13–16
 - managerial perspective, 11–16

Six Sigma (*continued*)

- Motorola and, 12
- overview, 9–11
- sigma scale, 23
- technical perspective, 16–25
- terminology origins, 23
- Six Sigma deployment. *See* deployment
- Six Sigma improvement. *See* improvement
- Six Sigma organization. *See* organization
- Six Sigma performance. *See* performance
- skewed distribution, dot plots/
histograms, 104
- skill levels
 - Black Belt (*See* Black Belt)
 - Green Belt (*See* Green Belt)
 - Yellow Belt (*See* Yellow Belt)
- SL (specification limit), 124
- slope, scatter plot lines, 116–117
- soft savings, 76
- software
 - enterprise platforms, 281–282
 - introduction, 278
 - Linux, 281
 - Macintosh, 281
 - PC-Windows, 280–281
 - process optimization, 279–280
 - statistical analysis, 279
- software FMEA, 260
- SOPs (standard operating procedures),
process control plan and, 220–221
- sources, data collection, 265
- SPC (statistical process control)
 - continuous control charts, 230–235
 - control chart, 221
- special-cause variation, 35, 225, 228
- specifications
 - exceeding, 126–128
 - limits, 226
 - LSL (lower specification limit), 125
 - one-sided, 124
 - reasons for, 124
 - RUMBA, 125–126
 - SL (specification limit), 124
 - T (target), 125
 - two-sided, 124
 - USL (upper specification limit), 125
 - voice of the customer (VOC), 123
- square root, 94
- squared effects, multiple linear regression, 193
- squaring, distribution and, 93
- SSBI (Six Sigma Benchmarking
Association), 314
- SSE (summed squared error), 93, 190
- SSR (squared regression error), 189–190
- SSTO (total sum of the squared error),
residuals and, 189
- ST (short-term variation)
 - common-cause variation and, 97
 - formulas, 100
 - introduction, 35
 - LT (long-term) comparison, 102
 - overview, 96
 - standard deviation calculation, 98
- stability, data collection, 265
- standard deviation
 - confidence intervals, 176–178
 - ST calculation, 98
 - variation spread and, 95
- statistical analysis tools
 - ANOVA, 267, 271
 - basic stats, 267
 - description, 244
 - DOE (Design of Experiments), 267
 - exploratory analysis, 268, 276
 - marginal plots, 270
 - measurement systems analysis, 268
 - multivariate analysis, 268, 275–276
 - plots and charts, 267
 - probability plots, 270
 - process capability analysis, 267, 273–274
 - regression, 268, 275
 - reliability and survivability, 268, 278
 - software, 279
 - time series, 267
 - time series plots, 270
 - tolerance analysis, 267, 271–272
- statistical problem, projects, 65
- statistical process control. *See* SPC
(statistical process control)
- statistical solution, projects, 65
- statistics
 - distribution, 88
 - introduction, 85
 - measurement and, 87–88
 - reason for, 86
 - variation, 86

stem-and-leaf, exploratory analysis and, 276
 stepwise, regression and, 275
 strategies, needs assessment and, 67–68
 strength of effect, scatter plots, 115
 stretch goals, 303–304
 subgroup data, control charts
 collecting, 226
 rational subgroups, 230
 successful companies, 12
 super-experiments, 200–201
 superstitious delusions, correlation and, 31–32
 suppliers, manager tools and, 286
 sustain phase, deployment and, 58–59
 swim lanes, process modeling, 254
 symposia, 314–315
 synchronous mentored learning, 300

• T •

T (target), 125
t values, confidence intervals, 174
 Taguchi designs, DOE, 273
 tampering with the process, 218
 team members, project definition and, 292
 technical perspective
 introduction, 16
 product quality, 17–20
 service quality, 17–20
 transactional quality, 17–20
 technology
 leveraging, 312
 managerial perspective and, 14
 vendors, 317
 thinking domain
 description, 43
 thinking for breakthrough, 43–44
 time series, statistical analysis tool
 introduction, 267
 time-series analysis tools, 270
 time-series analysis
 autocorrelation, 271
 cross-correlation, 271
 decomposition, 270
 exponential smoothing, 271
 forecasting, 270
 moving averages, 270
 trending, 270
 time series plots, statistical analysis, 270

timing, data collection, 265
 to-be state, modeling, 255
 tolerance analysis, statistical analysis,
 267, 271–272
 tollgates (DMAIC), 42
 tools
 knowledge management, 298
 management tool types, 286
 manager tools, 283
 managerial perspective and, 14
 overview, 243
 process optimization tools, 244–266
 project management, 288–295
 statistical analysis tools, 244, 267–278
 trainers in Six Sigma, 318
 training representative, core team, 49, 50
 transactions
 processes, Poka-Yoke and, 240
 quality, 17–20
 transfer, data collection, 265
 transformations, problem transformations, 65
 Traxion, 279
 trending
 control charts, 222
 time-series analysis, 270
 trial-and-error approach to experiments,
 198–199
 two-sided specifications, 124
 Type-1 corrective action, process control
 and, 240
 Type-2 corrective action, process control
 and, 240

• U •

u charts (attribute data), 235, 238–239
 UCL (upper control limit), 223
 understandable (RUMBA), 126
 USL (upper specification limit), 125

• V •

variable data, 151–152
 variables, experiments, 197, 200
 variance
 beyond expected limits, 119–120
 definition, 94
 variation spread and, 95

variation

- assignable cause variation, 100
- best practices, 306
- causes, 34–35
- common-cause, 34, 97
- confidence intervals, 177–178
- description, 33
- distribution, range, 91–92
- expectation and, 33
- introduction, 32–33
- location, measures, 88–91
- long-term, 35
- LT (long-term variation), 99
- mean, 33, 89
- measurement and, 87
- measurement system sources, 154–156
- median, 90
- outliers, 90
- output, 100
- short-term, 35
- special-cause, 35, 100
- spread, 95
- statistics and, 86
- variance, 94
- variation obsession, 33
- wiggle, bump, and jitter, 22–23
- variation average, multi-modal histograms, 107
- variation mode, dot plots/histograms, 104–107
- variation range, multi-modal histograms, 107
- variation shape
 - dot plots, 104
 - histograms, 104
- Varyx, 280
- Visio, 280
- visual inspection system, scenario, 157
- visualization, experiments' main effects, 207–209
- vital few versus the trivial many, 39–40
- VOB (voice of the business)
 - needs assessment and, 68
 - SIPOC and, 248

VOC (voice of the customer)

- managerial perspective and, 13
- needs assessment and, 68
- process and, 128–148
- SIPOC and, 248
- specifications and, 125
- VOP (voice of the process), SIPOC and, 248

• W •

- WCBF (worldwide conventions and business forums), 315
- Web portals, 316
- whiskers (box and whisker plots), 108

• X-Y-Z

 x_i , measurement values in equations, 89

- X_s
 - experiments and, 196
 - 2^k factorial experiments, 203
 - χ^2 , 176–177

Y, experiments, 198

- Yellow Belt
 - characteristics, 53
 - description, 51
 - initiative roles, 55
 - manager tools and, 285
 - training, 52

 $Y = f(X) + \varepsilon$, 27–29

yield

- defect rate and, 138
- FTY (first time yield), 129–130
- hidden factory, 130–131
- measuring, 128–133
- metrics summary, 133
- output versus input, 128–129
- RTY (rolled throughput yield), 131–133
- traditional, 128–129

Z score. *See* Sigma (Z) score