

# Index

**Note:** The letter *f* following a page number indicates reference to a figure on that page.

## • Numerics •

2<sup>k</sup> factorial experiments  
  calculating interactions, 219–223  
  calculating main effects, 214–219  
  creating  $Y = f(X)$  equations, 227–228  
  determining significance, 224–226  
80-20 rule (Pareto Principle), 69–71, 145  
Z score, 155–157, 165–166, 170

## • A •

affinity diagrams, 53–57  
alternate venue psychology, 20  
Analyze (DMAIC phase), 3–4, 283–286  
attribute data  
  control chart selection for, 243  
  defined, 87  
  as ordinal data, 100  
  *p* chart, 255–260  
  *u* chart, 260–264  
attribute measurement systems, 146–149  
auditing measurement systems, 143–146  
Averages and Ranges chart, 252–255

## • B •

Bank of America, Six Sigma and, 16  
Black Belts  
  defined, 13  
  hiring, 21–22  
  organizational roles, 18  
  Six Sigma myths about, 286  
blocking and randomizing, 212–213  
Board of Directors, change management and, 28  
box and whisker plots, 110–114  
BPM (Business Process Management), 41  
brainstorming, 53–57  
breakthrough equation,  $Y = f(X) + \epsilon$  as, 9  
budgeting and costs  
  communicating, 39f  
  incentive compensation in, 29  
  for project completion, 288–290  
  Six Sigma myths of, 285–286  
  training program, 16, 21–22, 26  
business case writing tool, 45–46, 52  
business performance. *See also* measurement tools;  
  performance measurement  
  evaluating variation in, 9–12  
  incentive compensation, 29  
  IT systems, 41

Leadership Team responsibility for, 27–28  
maintaining improvements in, 241–242  
for project completion, 287–290  
Six Sigma contracting, 26  
Six Sigma implementation, 283–286  
  software tools, 40f  
  training responsibilities, 16  
Business Process Management (BPM), 41  
business-customer-process scorecard, 46–48

## • C •

C&E Matrix, 73–75  
calculations. *See also* formulas  
  confidence interval, 169–178  
  defects rate, 134–135  
  FTY, 131–132  
  interaction effects, 219–223  
  linking yield to defects, 136–137  
  main effects, 214–219  
  RTY, 132–134  
  sigma (*Z*) scores, 155–157  
  software aids in, 93  
  statistical significance, 224–226  
  variation, 89, 92–93  
capability measurement  
  improvement plan, 160–164, 168  
  indices, 160  
  sigma (*Z*) scores, 155–157  
  standard deviation, 155  
categorical data, 87  
cause-and-effect diagram. *See* fishbone diagrams  
cause-and-effect matrix. *See* C&E Matrix  
Champion/Senior Champion, 27–28, 30  
change management, 20, 28–30  
checklists and templates. *See also* worksheets  
  accessing this workbook for, 2–3  
  affinity diagram, 54–55, 57f  
  business problem areas, 46  
  business-customer-process scorecard, 47–48f  
  choosing training options, 22–24  
  Communications Plan, 38f, 39f  
  CT tree, 64  
  fishbone diagram, 59  
  FMEA, 76  
  Initiative Management Plan, 41–42  
  initiative preparation, 36  
  KBO, 14–15  
  objective statement, 51  
  problem statement, 48  
  process input control plan, 242  
  process management summary, 242  
  project initiation, 51  
  RUMBA, 130  
  SIPOC diagram, 71–73  
  software tools, 40f  
  Variation Journal, 8f

coefficient of determination ( $R^2$ ), 192

communications

- corporate culture, 19–20
- getting started in Six Sigma, 2
- initiatives, 31–33
- for project completion, 289
- role of environment in, 36
- Six Sigma elevator pitch, 33
- Six Sigma FAQ, 33–34
- standard tools of, 36–37

Communications Leader, 28

Communications Plan

- Communicator matrix, 34–35
- elements of the, 31–33
- types of, 31
- writing the, 38–39

complacency, 20

confidence interval

- defined, 169
- for means, 170–172
- for proportions, 176–178
- for standard deviation, 173–176, 180–182

continuous data, 87, 243, 252

continuous variable measurement, 150–152

Control (DMAIC phase)

- importance of, 239
- maintaining improvements in, 241–242
- Poka-Yoke, 240–241
- Six Sigma myths, 283–286
- using this workbook in, 3–4

control, variation, 7–8

control chart

- Averages and Ranges, 252–255
- I-MR chart, 249–251
- interpretation, 245–248
- $p$  chart, 255–260
- selection process, 242–245
- $u$  chart, 260–264

corporate culture

- implementing Six Sigma in, 19–20
- KBOs, 14
- Six Sigma myths, 283–286
- social network in the, 29

correlation

- fitted line, 190–196
- scatter plot, 115
- between variables, 185–189

correlation coefficient ( $r$ ), 185–186, 199

cost-cutting initiatives, Six Sigma and, 286

costs. *See* budgeting and costs

CT (Critical To) tree, 62–64

CTCs (critical-to-customer characteristics), 75

curve fitting, 190, 192–193

customers

- C&E Matrix, 73
- CTCs, 75
- deployment initiative and, 29
- VOC, 14, 46–48

## • D •

$d^2$  distribution, 173

data

- attribute, 87, 243, 255–264
- categorical, 87
- continuous, 87, 243, 252
- continuous variable, 150–152
- differentiating types of, 87–89, 100
- discrete, 87
- ordinal, 100
- variable, 87
- variation location in, 89–92
- variation spread in, 92–94

decision tree, 243f

defects rates. *See* DPMO (defects per million opportunities); DPO (defects per opportunity); DPU (defects per unit); performance measurement

defects/defectives, 136, 243

Define (DMAIC phase), 3–4, 283–286

deployment initiative

- aligning objectives and resources for, 13
- conducting training for, 21–24
- determining the training program, 16–21
- elevator pitch, 33
- implementation partners in, 24–26
- life cycle, 41–42
- planning the KBOs, 13–15
- selecting the leadership team for, 27–30
- Six Sigma myths, 283–286

Deployment Initiative Communications Plan, 31–32, 38f

Deployment Leader, 16, 23, 27–28

Design for Six Sigma (DFSS), 18

Design of experiments (DOE), 209–210

Designers, organizational roles of, 18

DFSS. *See* Design for Six Sigma (DFSS)

discrete data, 87

DMAIC (Define-Measure-Analyze-Improve-Control)

- project alignment to, 47f
- SIPOC diagrams, 71
- Six Sigma myths, 283–286
- using this workbook for, 2–3

dot plot, 90–91, 101–102, 107–110

DPMO (defects per million opportunities), 134–135

DPO (defects per opportunity), 134–135

DPU (defects per unit), 11–12, 134–135, 260–261

## • E •

EAI. *See* Enterprise Application Integration (EAI)

80-20 rule (Pareto Principle), 69–71, 145

e-learning, 20

elevator pitch, 33

Enterprise Application Integration (EAI), 41

examples

- accessing and locating, 4
- affinity diagram, 54–56

- applying  $Y = f(X) + \epsilon$ , 9–11
  - blocking and randomizing, 213
  - box and whisker plots, 111–113
  - business case tool, 46
  - C&E Matrix, 74
  - capability improvement plan, 161–162
  - Communicator matrix, 34–35
  - confidence interval, 171, 174–175, 177
  - control chart, 244, 247, 249, 253, 256, 261
  - correlation coefficient ( $r$ ), 186–188
  - CT tree, 62–63
  - differentiating data, 88
  - dot plot, 108–109
  - DPU, 135
  - fishbone diagram, 58–59
  - fitted line, 191–192, 193–195
  - FMEA, 76
  - FTY calculations, 131
  - interaction effects, 220–223
  - linking yield to defects, 136
  - main effects, 214
  - measured-to-observed variation, 151
  - MSA, 144–145, 147–149
  - objective statement, 50
  - Poka-Yoke, 240
  - problem statement, 48–49
  - process flow maps, 61
  - RTY, 133
  - scatter plot, 115–117
  - short-term vs. long-term, 95–97
  - sigma ( $Z$ ) score, 156, 158
  - SIPOC diagram, 72
  - time series charts, 119–120
  - variation location, 89–91
  - variation spread, 93
  - for  $Y = f(X)$  equations, 227
  - exercise, “Solve It”
    - affinity diagram, 56–57
    - blocking and randomizing, 213–214
    - box and whisker plots, 113–114
    - C&E Matrix, 74–75
    - capability improvement plan, 162–164
    - confidence interval, 172, 175–178
    - control chart, 244, 248, 251, 255, 259, 264
    - correlation coefficient ( $r$ ), 188–189
    - creating business cases, 46
    - CT tree, 64
    - defects rates, 135–136
    - differentiating data, 88–89
    - dot plot and histogram, 109–110
    - fishbone diagram, 59
    - fitted line, 191–192, 196
    - FMEA, 76–79
    - FTY calculations, 132
    - interaction effects, 223
    - linking yield to defects, 136–137
    - main effects, 218–219
    - measured-to-observed variation, 152
    - MSA, 145–147
    - objective statement, 51
    - Poka-Yoke, 240–241
    - problem statement, 49
    - process flow map, 61–62
    - RTY, 133–134
    - scatter plot, 117–118
    - sigma ( $Z$ ) score, 157, 159
    - SIPOC diagram, 72–73
    - time series charts, 120
    - variation, 91–92, 94, 97–99
    - for  $Y = f(X)$ , 228
  - exercise solutions
    - box and whisker plots, 123–126
    - brainstorming, 64
    - C&E Matrix, 82
    - calculating correlation coefficient, 197–200
    - capability measurement, 165–168
    - confidence interval, 179–182
    - control chart, 266–279
    - CT tree, 67–68
    - defects rate, 139–140
    - defining a project, 52
    - dot plot and histogram, 121–123
    - fishbone diagram, 64–65, 80
    - fitted line, 201–203
    - FMEA, 83
    - FTY, 138
    - MSA, 153–154
    - Pareto diagram, 80
    - Poka-Yoke, 265–266
    - process flow map, 66–67
    - residual error, 204–208
    - RTY, 139
    - scatter plot, 126–127
    - SIPOC, 81
    - time series charts, 127–128
    - $2^k$  factorial experiments, 229–236
    - variation, 100–106
    - for  $Y = f(X)$  equations, 236–237
  - expansion phase, 32, 41–42
  - experimental design, 209–210
- 
- **F** ●
  - $F$  distribution, 173–175
  - factorial experiments, 209–214
  - failure, variation as cause of, 7–8
  - Failure Modes Effects Analysis (FMEA). *See* FMEA (Failure Modes Effects Analysis)
  - FAQ. *See* frequently asked questions (FAQ)
  - financial performance, responsibility for, 28
  - fishbone diagrams, 57–59, 64–65, 70–71
  - FMEA (Failure Modes Effects Analysis), 76–79
  - formulas. *See also* calculations
    - accessing and locating, 4
    - calculation software for, 1
    - conventions used in this book, 2
    - $Y = f(X)$  equations, 9, 227–228

frequently asked questions (FAQ), 33–34  
 FTY (first time yield), 131–132  
 functional sub-optimization, 14

## • G •

General Electric, Six Sigma and, 26, 285  
 goals  
   establishing objectives, 49–51  
   KBO checklist, 14  
   for successful completion of, 289  
 Green Belts, roles of, 18

## • H •

histograms, displaying variation by, 107–110  
 Honeywell, Six Sigma and, 285

## • I •

implementation myths of Six Sigma, 283–286  
 implementation partners, selecting, 24–25  
 Improve (DMAIC phase), 3–4, 14, 283–286  
 I-MR (individuals and moving range) chart, 249–251  
 Information Technology (IT) Architecture, 39–41  
 initialization phase, 32, 36, 41–42  
 Initiative Management Plan, 41–42  
 input diagrams  
   affinity diagram, 53–57  
   CT tree, 62–64  
   fishbone diagram, 57–59, 70–71  
   Pareto Principle (80-20 rule), 69–71  
   SIPOC diagrams, 71–73  
 inputs  
   C&E Matrix, 73  
   CTCs as, 75  
   identifying, 53–54  
   Pareto diagram for, 69–71  
   prioritizing, 69, 80  
    $Y = f(X) + \epsilon$ , 9–11  
 interaction effects, 219–223  
 interpolation, 166  
 inventory measurement, 144–145  
 Ishikawa diagram, 57–59

## • K •

KBO (key business objectives), 2, 13–15. *See also* objectives

## • L •

leadership  
   communications initiatives, 31  
   importance of engaged management in, 23

for project completion, 287–290  
 role of the Champion in, 28  
 social network, 29

Leadership Team, 27–30, 53–57  
 Learning Management System (LMS), 20  
 life cycle, initiative, 41  
 linear regression, 190–196  
 linear relationships, 185–186  
 long-term capability index, 160  
 long-term variation, 94–99, 158

## • M •

main effects, 214, 217  
 make vs. buy decision process, 22f  
 management  
   initiative leadership, 36  
   for project completion, 287–290  
   Six Sigma proficiency for, 1  
   Six Sigma training program, 16–26  
   software tools, 40f  
 Master Black Belts, role of, 18, 21–22  
 mathematical calculations. *See* calculations;  
   formulas; statistics  
 mean, 89, 170–172  
 Measure (DMAIC phase), 3–4, 283–286  
 measured-to-observed variation, 150–152  
 measurement system analysis. *See* MSA  
   (measurement system analysis)  
 measurement tools. *See also* performance  
   measurement  
   importance of communications, 31  
   IT systems, 41  
   management software, 40f  
   practitioner software, 40f  
   SMART objective statements, 50  
 measures of variation, 89–92, 94, 104  
 median as measure of variation, 89  
 Minitab calculation software, 1  
 mode as measure of variation, 89  
 Motorola, Six Sigma and, 23, 284–285  
 MSA (measurement system analysis)  
   attribute analysis, 146–149, 154  
   audit, 143–146  
   continuous variable data, 150–152

## • N •

new-hire training, 16

## • O •

Objectives, 49–51, 287–288. *See also* KBO (key business objectives)  
 off-site retreats, 20, 36  
 ordinal data, 100

## outcomes

- C&E Matrix, 73
  - CT tree, 62–64
  - linking yield to defects, 136
  - Pareto Principle (80-20 rule), 69, 145
  - process flow maps, 60–62
  - $Y = f(X) + \epsilon$ , 9–11
- outliers, 89, 108
- outsourcing
- make vs. buy decision process, 23
  - Six Sigma myths, 285–286
  - training program, 21–23

● **p** ●

- p* chart, 255–260
- Pareto Principle (80-20 rule), 69–71, 145
- performance measurement. *See also* business performance; measurement tools
- attribute measurement systems, 146–149
  - continuous variable measurement, 150–152
  - control charts, 242–248
  - creating specifications for, 129–130
  - defects rate calculations, 134–135
  - FTY calculations, 131–132
  - linking yield to defects, 136–137
  - MSA, 143–146
  - for project completion, 287–290
  - sigma (*Z*) scores, 155–158
  - Six Sigma implementation, 283–286
  - training program, 17–19
- Poka-Yoke, 239–241, 266
- problem statements, 48–49, 52
- problem-solving
- applying Six Sigma to, 2–3, 45–46
  - brainstorming as, 53–54
  - KBO, 13–15
  - Six Sigma myths, 283–286
  - SMART objective statements, 50
- process alignment, 15
- process behavior charts, 119–120
- process flow maps, 60–62, 66–67, 71
- process input control plan, 241–242
- process management summary, 241–242
- process modeling, 283
- project charter, 36f, 288
- Project Communications Plan, 31–32, 38f
- project management, 40, 290
- projects
- creating ideas for, 45–46
  - defining objectives, 13–15, 49–51
  - prioritizing and aligning, 46–48
  - problem statements, 48–49
  - Six Sigma myths about, 286
  - successful completion, 45
  - successful completion of, 287–290
- proportion defective, 255
- proportions, 176–178

● **R** ●

- randomization and blocking, 212–213
- range as a measure of variation, 92
- ranking inputs and outputs, 73–75
- refresher training, 16
- residual error ( $e_i$ ), 192
- resistance to change. *See* change management
- risks and pitfalls
- accessing and locating, 4
  - change management, 29
  - cost-cutting initiatives, 285
  - DFSS undertraining, 19
  - measuring variation, 94
  - scoping projects, 287
  - training program, 16, 26
- RPN (risk priority number), 78–79, 83
- RTY (rolled throughput yield), 11–12, 132–134, 140
- RUMBA test of specifications, 129–130

● **S** ●

- scatter plots, 114–118, 127, 192
- Service-Oriented Architectures (SOA), 41
- shareholders. *See* stakeholders
- short-term capability index, 160
- short-term variation, 94–99, 158
- sigma (*Z*) score, 155–157, 170
- sigma shift, 158
- SIPOC diagrams, 71–73
- Six Sigma
- defined, 1
  - frequently asked questions (FAQ), 33–34
  - implementation myths, 283–286
  - incentive compensation and, 29
  - initiative life cycle, 41–42
  - Motorola origins of, 23
  - organizational roles, 17–18
  - performance measurement, 129
  - pricing and contracting, 26
  - software tools, 40f
  - statistical sampling, 169
  - for successful completion of, 287–290
  - training options for, 21–24
- Six Sigma initiative. *See* deployment initiative; projects
- SMART objective statements, 50
- SOA. *See* Service-Oriented Architectures (SOA)
- social network, identifying, 29
- software
- make vs. buy decision process, 22
  - process modeling, 283
  - selecting, 39–40
  - for Six Sigma calculations, 1
  - statistics, 93
- “Solve It” exercises. *See* exercise, “Solve It”
- special causes events, 245–247
- specifications, 129–130, 160

stakeholders  
 communications, 33–35  
 identifying, 28–29  
 maintaining support of, 289–290

standard deviation  
 calculating confidence intervals for, 173  
 capability measurement, 155  
 as a measure of variation, 92, 193  
 short-term vs. long-term, 158

statistical process control chart. *See* control chart

statistical sampling, 169

statistics  
 assumptions about, 2  
 calculating variation location, 89–92  
 determining significance, 224–226  
 interaction effects, 219–223  
 main effects, 214–219  
 measuring variation spread, 92–94  
 sampling distribution, 169

Suppliers-Inputs-Process-Outputs-Controls (SIPOC).  
*See* SIPOC diagrams

sustaining phase, 32, 41–42

## • T •

*t* values, 170

templates. *See* checklists and templates;  
 worksheets

time series charts, 119–120

training program  
 corporate culture and, 19–20  
 defining the, 20–21  
 managing the, 16–17  
 options for conducting the, 21–24  
 organization and scope, 17–19  
 pricing and contracting, 26  
 selecting a, 16  
 selecting implementation partners, 24–25  
 Six Sigma myths, 283–286

2<sup>k</sup> factorial experiments  
 calculating interactions, 219–223  
 calculating main effects, 214–219  
 creating  $Y = f(X)$  equations, 227–228  
 determining significance, 224–226

## • U •

*u* chart, 260–264

U. S. Air Force, Six Sigma and, 16

## • V •

variable data, 87

variables  
 blocking and randomizing, 212–214  
 conventions in this workbook, 2

correlation between, 185–189  
 curve fitting to, 190–192  
 interaction effects, 219–223  
 main effects, 214–219  
 residual error and unexplained, 192–196

variance as a measure of variation, 92

variance ratios, 150–152

variation  
 assessing the impact of, 11–12  
 calculating, 89–99, 103  
 confidence interval, 169  
 evaluating with  $Y = f(X) + \epsilon$ , 9–10  
 FMEA, 76  
 identifying causes of, 57  
 measured-to-observed, 150–152  
 recognizing and journaling, 7–8  
 short-term vs. long-term, 94–99  
 Six Sigma goals, 7  
 special causes, 245–247

variation displays  
 box and whisker plots, 110–114  
 dot plot and histogram, 107–110  
 scatter plots, 114–118  
 time series & process behavior charts, 119–120

Variation Journal, 8f

Voice of the Business (VOB), 14, 47–48  
 Voice of the Customer (VOC), 14, 47–48, 73  
 Voice of the Process (VOP), 47–48

## • W •

worksheets. *See also* checklists and templates  
 calculating RTY and DPU, 12f  
 hardware/software selection, 39f  
 KBO alignment, 15f  
 Leadership Team membership, 30f  
 make vs. buy, 24f  
 Skills Assessment, 17f  
 training program, 19f, 25f  
 $Y = f(X) \epsilon$ , 10f, 11f

## • Y •

$Y = f(X) + \epsilon$   
 as breakthrough equation, 9  
 C&E Matrix, 73  
 example for applying, 9–11  
 identifying inputs in, 53  
 $Y = f(X)$  equations, 227–228  
 Yellow Belts, organizational roles of, 18  
 yield and defects rates. *See* performance  
 measurement

## • Z •

Z score, 155–157, 165–166, 170