

# CONTENTS

<b>FOREWORD</b>		<b>xvii</b>
<i>Frank Ianna</i>		
<b>PREFACE</b>		<b>xix</b>
<b>ACKNOWLEDGMENTS</b>		<b>xxi</b>
<b>PART I OVERVIEW</b>		<b>1</b>
<b>Chapter 1 INTRODUCTION</b>		<b>3</b>
<i>H. Anthony Chan and Paul J. Englert</i>		
1.1 Synopsis of Reliability Trends and Aim of Book		3
1.2 Background of Military and Industrial Stress Testing Practices		5
1.3 Overview of the AST Handbook		6
References		9
<b>Chapter 2 PRINCIPLES OF STRESS TESTING</b>		<b>10</b>
<i>H. Anthony Chan and Paul J. Englert</i>		
2.1 Rationale for Stress Testing		11
2.1.1 Product Robustness		11
2.1.2 AST and Accelerated Testing		12
2.1.3 AST and the Bath-Tub Curve		14
2.1.4 Bimodal Product Strength Distribution		14
2.1.5 Relevance of AST Failures		17
2.1.6 Types of Stress Failures		18
2.2 Stress Testing Technical and Implementation Issues		19
2.2.1 Modes of AST		19
2.2.2 Other Forms of Stress Testing		20
2.2.3 Stress Stimuli and Flaws Precipitated by Them		21
2.2.4 Stress Stimuli Selection		22
2.2.5 Stress Level Determination		23
2.2.6 Safety Testing		23
2.2.7 Fault Simulation and Detection Issues		24
2.2.8 Form of Product to Test		25
2.3 Economic Issues		27

2.3.1 Benefits	27
2.3.2 Cost of AST	27
2.3.3 Optimizing the Application of AST	28
References	29
<b>PART II PROCESS AND GUIDELINES</b>	<b>31</b>
<b>Chapter 3 STRESS TESTING PROGRAM: GENERIC PROCESSES</b>	<b>33</b>
<i>H. Anthony Chan and Paul J. Englert</i>	
3.1 Overview of the Stress Testing Strategy	33
3.1.1 Select AST Options	36
3.2 Design Stress Testing (D-AST)	36
3.2.1 Plan Program (A)	36
3.2.2 Baseline Product (B)	36
3.2.3 Take Corrective Action (C)	37
3.3 Manufacturing Qualification Stress Testing (MQ-AST)	38
3.3.1 Plan Program (A)	39
3.3.2 Baseline Product (B)	39
3.3.3 Take Corrective Action (C)	39
3.3.4 Develop Manufacturing AST Regimen (D)	39
3.3.5 Demonstrate Safety of the AST Regimen (E)	40
3.3.6 Perform Manufacturing AST (F)	40
3.4 Periodic Qualification Stress Testing (PQ-AST)	40
3.5 Production Sampling Stress Test (PS-AST)	41
3.5.1 Plan Program (A)	41
3.5.2 Develop Manufacturing AST Regimen (D)	41
3.5.3 Perform Manufacturing AST Regimen (F)	42
3.5.4 Take Corrective Action (C)	42
3.5.5 Optimize Manufacturing AST Regimen (G)	43
3.6 Full Production Stress Testing (FP-AST)	43
<b>Chapter 4 STRESS TESTING PROGRAM SUBPROCESSES</b>	<b>44</b>
<i>H. Anthony Chan and Paul J. Englert</i>	
4.1 Plan Program Subprocess (A)	44
4.1.1 TASK 1: Form Team and Develop AST Strategy	44
4.1.2 TASK 2: Review and Issue AST Strategy	46
4.1.3 TASK 3: Write the AST Plan	47
4.1.4 TASK 4: Review and Issue AST Plan	47
4.1.5 TASK 5: AST Tools Realization	48
4.2 Baseline Product Subprocess (B)	50
4.2.1 TASK 1: Baseline Product	50
4.3 Take Corrective Action Subprocess (C)	51
4.3.1 TASK 1: Analyze AST Results	51
4.3.2 TASK 2: Suggest and Review Corrective Actions	53
4.3.3 TASK 3: Develop AST Verification Plan for Corrective Action	54
4.3.4 TASK 4: Issue Summary of Lessons Learned	55
4.4 Develop Manufacturing Stress Testing Regimen Subprocess (D)	55
4.4.1 TASK 1: Determine the Form of Product to be Tested	55
4.4.2 TASK 2: Determine What Stress Stimuli Are Effective	56
4.5 Demonstrate Safety of the Stress Testing Regimen Subprocess (E)	57
4.5.1 TASK 1: Develop AST Safety Strategy	58
4.5.2 TASK 2: Write AST Safety Qualification Plan	58

4.5.3 TASK 3: Execute Safety Qualification Plan	59
4.5.4 TASK 4: Analyze Safety Test Data	60
4.5.5 TASK 5: Certify Safety of Candidate AST Regimen	61
4.6 Perform Manufacturing Stress Testing Subprocess (F)	61
4.6.1 TASK 1: Execute AST Plan	61
4.7 Optimize the Manufacturing Stress Testing Regimen Subprocess (G)	62
4.7.1 TASK 1: Analyze Manufacturing AST Regimen Data	62
4.7.2 TASK 2: Select Manufacturing AST Mode or Regimen	64
4.7.3 TASK 3: Develop Evaluation Plan for Trial AST Regimen	64
4.7.4 TASK 4: Conduct Evaluation of Trial AST Regimen	65

## **Chapter 5**      **GUIDELINES FOR DESIGN AND MANUFACTURING STRESS TESTING**      **66**

*H. Anthony Chan and Paul J. Englert*

5.1 AST Test Strategy	66
5.2 AST Plan	68
5.3 Sample Size Selection for Design AST	69
5.4 Typical Stress Stimuli and Associated Product Flaws	70
5.5 Recommended Stress Levels	71
5.6 Baseline Product Test Procedures	77
5.7 Failure Mode Analysis and Root Cause Analysis	83
5.7.1 Failure Types and Modes Found During Stress Testing	85
5.8 Corrective Action and Product Ruggedization	87
5.8.1 Design AST Database	87
References	90

## **PART III THEORY**      **91**

### **Chapter 6**      **ECONOMICS AND OPTIMIZATION**      **93**

*H. Anthony Chan and Paul J. Englert*

6.1 Guidelines for Optimizing Manufacturing Stress Testing	93
6.1.1 Product Attributes	93
6.1.2 Environment for Stress Testing	94
6.1.3 The Optimization Process	95
6.1.4 Effectiveness of the Stress Regimen	96
6.1.5 A/B Comparisons	97
6.2 Formulation	97
6.3 Reliability Objective	98
6.4 Types of Failures Revisited	98
6.5 Distribution of Environmental Stresses	98
6.6 Effect of Stress Testing	100
6.7 Reliability Requirements	101
6.8 Requirement on Service-Life Fraction Failed	101
6.9 Requirement on Product Strength Distribution	102
6.10 Examples	103
6.10.1 1 in 100 Service-Life Fraction Failed Requirements	104
6.10.2 1 in 1000 Service-Life Fraction Failed Requirements	104
6.11 Economic Issues and Optimization	105
6.11.1 Reduction in Field Failure Rate	105
6.11.2 Potential Benefits	105
6.11.3 Potential Costs	106

6.12	Net Benefit	106
6.13	Optimization	107
6.14	Product Considerations	108
6.15	Economic Summary	108
	References	108
<b>Chapter 7</b>	<b>RELIABILITY GROWTH</b>	<b>109</b>
	<i>Clifton J. Seusy</i>	
7.1	What Is Reliability Growth?	109
7.2	How Many Units Must Be Tested?	110
	7.2.1 Binomial Probabilities	110
7.3	Failure Mode Distribution	111
	7.3.1 Mathematical Substantiation	113
	7.3.2 Kuklinski Curves	114
7.4	How Are These Units Acquired?	118
	7.4.1 Prototype Production	118
	7.4.2 Final Product Production	119
7.5	The Success of Failures Attained by Stress Testing	120
	7.5.1 Generic Stresses	120
	7.5.2 Product-Specific Stresses and Stress Levels	120
	7.5.3 Relevance of Stress Failures	121
	7.5.4 Addressing All Failure Modes	122
	7.5.4.1 Design Defect Tracking	123
	7.5.4.2 Failure Analysis	124
7.6	Results	124
7.7	Conclusions	125
	Acknowledgments	125
	References	126
<b>Chapter 8</b>	<b>OVERVIEW OF THE FAILURE ANALYSIS PROCESS FOR ELECTRICAL COMPONENTS</b>	<b>127</b>
	<i>Greg Pfeiffer</i>	
8.1	Definition of Failure Analysis	127
8.2	The Benefits of Performing Failure Analysis	127
8.3	Overview of the Failure Analysis Process for Electrical Components	128
	8.3.1 Understand the Problem	128
	8.3.2 Examine the Component Package with a Low-Power Microscope	128
	8.3.3 Verify the Failure	128
	8.3.4 Nondestructive Evaluation	128
	8.3.5 Stop, Think, and Plan!	129
	8.3.6 Decapsulate the Device	129
	8.3.7 Examine the Interior of the Package and the Die Surface	129
	8.3.8 Conduct a Physical Analysis	129
	8.3.9 Evaluate the Data and Come to a Conclusion	129
	8.3.10 Develop a Corrective Action Recommendation	129
	8.3.11 Write and Issue a Report (as Required by the Customer)	130
	8.3.12 Archive the Data and Samples	130
	8.3.13 Follow Up on Customer's Corrective Action Results	130
8.4	Tools for Component Failure Analysis	130
	8.4.1 Basic (Tools that Every Lab Needs)	130
	8.4.2 Additional Tools	131
8.5	Personnel for Component Failure Analysis	131
8.6	Challenges Facing Failure Analysts in the Future	131

8.7 What the Customer Can Do to Optimize the Failure Analysis Process	132
References	132

**PART IV EQUIPMENT AND TECHNIQUES 135**

**Chapter 9 ACCELERATED STRESS TESTING EQUIPMENT AND TECHNIQUES 137**  
*Charles Felkins*

9.1 Introduction	137
9.2 Thermal Equipment	137
9.2.1 Operating Temperature Range	138
9.2.2 Temperature Rate of Change	138
9.2.3 Mechanical Refrigeration versus Liquid Nitrogen (LN <sub>2</sub> ) Cooling	140
9.2.4 LN <sub>2</sub> Implementation	141
9.3 Vibration Equipment	142
9.3.1 Issues for Repetitive Shock Machines Using Pneumatic Vibrators	144
9.3.2 Multi-Axial Considerations for Repetitive Shock Machines	145
9.3.3 Table Resonances for Repetitive Shock Machines	147
9.3.4 g <sub>RMS</sub> versus Peak G Stress	147
9.4 Combined Thermal and Vibration Equipment	147
9.5 Ancillary Mechanical Equipment for Stress Testing	148
9.5.1 Fixturing for Vibration Stressing	148
9.5.2 Printed Wiring Board Card Cages Used for Stress Testing	149
9.6 Environmental Analysis Equipment Used for Stress Testing	152
9.7 Electrical Test Equipment and Software Used for Stress Testing	153
9.7.1 AST Test Equipment Hardware	153
9.7.2 AST Test Equipment Software	153
9.8 Other Stress Options	154

**Chapter 10 VIBRATION AND SHOCK INPUTS IDENTIFY SOME FAILURE MODES 155**  
*Wayne Tustin*

10.1 Why Important?	155
10.2 Vibration Measurements	155
10.2.1 Prior Knowledge	155
10.2.2 Vibration and Shock Measurement—Units	157
10.2.3 Vibration and Shock Sensors (Field and Laboratory)	159
10.2.3.1 Displacement Sensors	159
10.2.3.2 Velocity Sensors	160
10.2.3.3 Accelerometers	160
10.2.3.4 Force Sensors	161
10.2.4 Signal Conditioning	162
10.2.5 Display and Recording Instruments	163
10.2.6 Sources of Sensor Error	163
10.3 Controllable Sources of Vibration and Mechanical Shock	164
10.3.1 Electrodynamic (Electromagnetic) Shakers	164
10.3.1.1 Shaker Armature	164
10.3.1.2 Magnetic Field	165
10.3.1.3 Alternating Current Generates Force	165
10.3.1.4 Force Ratings	165
10.3.1.5 Vertical or Horizontal Thrusting	167

10.3.1.6	Isolation from Building	167
10.3.2	Power Amplifiers	167
10.3.2.1	Delivering Adequate Alternating Current for Shaker Driver Coil	167
10.3.2.2	Momentary Power Peaks	168
10.3.2.3	Importance of Low Distortion	168
10.3.2.4	Direct Current for Shaker Field Winding	168
10.3.3	Controls	168
10.3.3.1	Controls for Sine Vibration Testing	169
10.3.3.2	Controls for Random Vibration Testing	169
10.3.3.3	Tolerances	169
10.3.3.4	Abort Limits	169
10.3.3.5	Controls for Shock Testing	170
10.3.4	Test Fixtures	170
10.4	Characteristics of Shock, Sine, and Random Vibration	170
10.4.1	Mechanical Shock Pulse	170
10.4.2	Sinusoidal Vibration and Its Effects	172
10.4.3	Random Vibration and Its Effects	173
10.4.4	Amplitude Probability Density	174
10.4.5	Acceleration Spectral Density	176
10.5	Multi-Axis Excitation	176
10.6	Repetitive Shock Machines for Multi-Axis Stress Testing	178
10.7	Using Random Vibration and Repetitive Shock for Stress Testing	178
10.7.1	What Spectrum?	179
10.7.2	What Intensity?	180
10.7.3	For How Long?	180
10.7.4	Is Our Production Screening Damaging Good Hardware?	180
<b>Chapter 11</b>	<b>RELATIVE EFFECTIVENESS OF THERMAL CYCLING VERSUS BURN-IN</b>	<b>182</b>
	<i>King Lo and Frank LoVasco</i>	
11.1	Introduction	182
11.2	Results for Thermal Cycling Alone	183
11.3	Intermittents and First Events	183
11.4	Thermal Cycling versus Burn-In	185
11.5	Failure Mechanisms	186
11.6	Conclusion	187
	Acknowledgments	188
<b>Chapter 12</b>	<b>ACCELERATED QUALIFICATION OF ELECTRONIC ASSEMBLIES UNDER COMBINED TEMPERATURE CYCLING AND VIBRATION ENVIRONMENTS: IS MINER'S HYPOTHESIS VALID?</b>	<b>189</b>
	<i>Kumar Upadhyayula and Abhijit Dasgupta</i>	
12.1	Introduction	190
12.2	Combined Temperature and Vibration Accelerated Life Tests	191
12.3	The Macroscopic Incremental Damage Superposition Approach (Macro-IDSA)	194
12.4	The Micromechanistic Incremental Damage Superposition Approach (Micro-IDSA)	197
12.5	Conclusions	200
	Acknowledgments	201
	References	201

<b>Chapter 13</b>	<b>LIQUID ENVIRONMENTAL STRESS TESTING (LEST)</b>	<b>203</b>
	<i>Paul J. Englert</i>	
	13.1 Advantages of Liquid Environmental Stress Testing	203
	13.2 Liquid Environmental Stress Testing Facility	204
	13.2.1 Overview of LEST Facility Features	204
	13.3 Thermal Considerations in Liquid Environmental Stress Testing	208
	13.4 Conclusions	214
	References	214
<b>Chapter 14</b>	<b>SAFETY QUALIFICATION OF STRESS TESTING</b>	<b>216</b>
	<i>S. Rajaram</i>	
	14.1 Stress Testing Safety Qualification Program	217
	14.1.1 Generic Component Qualification	219
	14.1.1.1 IC Qualification	219
	14.1.1.2 Discrete Component Qualification	220
	14.1.2 Specific Code Qualification	220
	14.1.2.1 The Qualification Process	221
	14.1.2.2 AST with Voltage Bias	221
	14.1.2.3 THB Testing	222
	14.1.2.4 Product Destruct Limit Testing	223
	14.2 Safety Qualification Programs for Other Types of Stresses	223
	References	224
<b>PART V</b>	<b>BEST PRACTICES CASE STUDIES IN COMPUTER, COMMUNICATIONS, AND OTHER INDUSTRIES</b>	<b>227</b>
<b>Chapter 15</b>	<b>PRODUCTION AST WITH COMPUTERS USING THE TAGUCHI METHOD</b>	<b>229</b>
	<i>Dennis E. Pachuki</i>	
	15.1 Introduction	229
	15.2 Objectives	230
	15.3 Stress Overview	230
	15.4 Stress Screen Designs	230
	15.4.1 Temperature Range	230
	15.4.2 Temperature Change Rate	231
	15.4.3 Power Cycling	231
	15.4.4 Vibration Screen Determination	231
	15.4.5 Fixture Design	232
	15.4.6 Vibration Stress Duration	232
	15.4.7 Diagnostic Monitoring	232
	15.5 Experiment Overview	232
	15.5.1 Test Process Product Flow	233
	15.6 The Taguchi Method	234
	15.6.1 Sample Size Selection	235
	15.7 Response Variable Results and Conclusions of the Taguchi Experiment	236
	15.7.1 Triaxial Random Vibration	236
	15.7.2 Temperature Cycling	237
	15.7.3 Power Cycling	237

	15.8	Intra-Experiment Summary	237
	15.9	Taguchi Method Conclusion	238
	15.10	Terms	239
		Acknowledgments	239
		References	239
<b>Chapter 16</b>		<b>DESIGN AST WITH VENDOR ELECTRONICS</b>	<b>240</b>
		<i>Charles Schinner</i>	
	16.1	Introduction	240
	16.2	The Test-Analyze-Correct-Verify Process	240
	16.3	Accelerated Reliability Techniques (ART)	242
	16.3.1	Stress Tool Box	243
	16.3.2	Broad Spectrum Stress Portfolio	243
	16.4	Original Equipment Manufacturer (OEM) Power Supply Example	244
	16.5	Conclusions	251
		Acknowledgments	252
		References	252
<b>Chapter 17</b>		<b>DESIGN AND PRODUCTION AST WITH POWER SUPPLIES</b>	<b>253</b>
		<i>Donald Dalland</i>	
	17.1	Background	253
	17.1.1	Switching Power Supplies	253
	17.2	STRIFE in New Product Development (Design AST)	253
	17.2.1	Vibration	254
	17.2.2	Thermal Test	255
	17.2.3	Electrical Overstress	256
	17.2.4	Power Cycling	256
	17.2.5	Results	256
	17.2.6	Conclusions with STRIFE in Product Development (Design AST)	257
	17.3	ESS in Manufacturing (Production AST)	257
	17.3.1	Burn-In	257
	17.3.1.1	Burn-In Conditions	258
	17.3.1.2	Results	258
	17.3.2	Vibration Screening	259
	17.3.2.1	Conditions	259
	17.3.2.2	Results	260
	17.3.3	Conclusions with ESS in Manufacturing (Production AST)	260
	17.4	Final Conclusions	261
		Acknowledgments	262
<b>Chapter 18</b>		<b>DESIGN AND PRODUCTION AST WITH COMPUTERS</b>	<b>263</b>
		<i>Edmond L. Kyser</i>	
	18.1	Background	263
	18.1.1	A Massively Parallel RISC-Based Server	263
	18.2	The ESS Program	263
	18.2.1	Integration	264
	18.3	Conclusions	268
		Acknowledgments	268
		Definitions and Acronyms	268
		Reference	268

<b>Chapter 19</b>	<b>QUALIFICATIONS AND PRODUCTION SAMPLING AST WITH PRINTED CIRCUIT BOARDS</b>	<b>269</b>
	<i>Harry McLean</i>	
	19.1 Introduction	269
	19.2 Proposed Test and Theory	270
	19.3 Ongoing Monitoring of the Production Process	271
	19.4 Screen Development	273
	19.5 Equipment	274
	19.6 Results of the Initial Testing	275
	19.7 Conclusions	278
	Acknowledgments	280
	Glossary	280
	References	281
<b>Chapter 20</b>	<b>MANUFACTURING AST WITH TELECOMMUNICATION PRODUCTS</b>	<b>282</b>
	<i>T. Paul Parker and Gordon L. Harrison</i>	
	20.1 Introduction	282
	20.2 EST During Product Design (Design AST)	284
	20.3 Production EST (AST)	285
	20.3.1 Techniques of Production EST (AST)	286
	20.3.2 FMA and Corrective Action	287
	20.4 Production EST (AST) Studies at AT&T	288
	20.4.1 Facilities Hardware and Software	289
	20.4.2 Thermal Profile	291
	20.5 Results of the Thermal Cycling Studies	291
	20.5.1 Phase I Study	292
	20.5.2 Phase IIa	292
	20.5.3 Phase IIb	294
	20.5.4 Phase III	294
	20.5.5 Phase IV	296
	20.5.6 Future Studies	296
	20.5.7 Conclusion	297
	Acknowledgments	297
	References	298
<b>Chapter 21</b>	<b>PRODUCTION AST WITH COMPUTER DISKS</b>	<b>300</b>
	<i>Kevin Granlund</i>	
	21.1 Introduction	300
	21.2 Growing Reliability	301
	21.3 Problem	302
	21.4 Case Study	302
	21.5 Product Flow	303
	21.6 Profile Utilized	304
	21.7 A Look at the Failure Mechanisms	304
	21.8 The Bottom Line	306
	21.9 Conclusion	307
	References	307

<b>Chapter 22</b>	<b>BENCHMARKING</b>	<b>308</b>
	<i>Henry Malec</i>	
22.1	Introduction to Benchmarking	308
22.1.1	Traditional Benchmarking	310
22.1.2	Product Benchmarking	313
22.1.3	AST Benchmarking	316
22.2	The AST Benchmarking Process	317
22.3	Benchmarking Partnerships—Otis Elevator Company and United Technologies/3Com Corporation (U.S. Robotics)	325
22.4	Benchmarking AST Survey Data	327
22.5	Summary	329
	Acknowledgments	329
	References	329
	Appendix A Environmental Stress Screening Questionnaire—1997	330
	Appendix B Environmental Stress Screening Questionnaire— 1996 & 1997 Results	333
	<b>GLOSSARY OF STRESS TESTING TERMINOLOGY</b>	<b>338</b>
	<b>BIBLIOGRAPHY</b>	<b>340</b>
	<b>INDEX</b>	<b>365</b>
	<b>EPILOGUE</b>	<b>369</b>
	<b>ABOUT THE EDITORS</b>	<b>371</b>